

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9705070115 DOC.DATE: 97/05/02 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH.NAME AUTHOR AFFILIATION
 HOVEY,R.J. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards one copy of newly issued EPIP O-EPIP-20132,
 "Technical Support Ctr Activation & Operation" & "Recovery
 Plan."

DISTRIBUTION CODE: A045D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1 + 113
 TITLE: OR Submittal: Emergency Preparedness Plans, Implement'g Procedures, C


NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-3 PD	1 1	CROTEAU,R	1 1
INTERNAL:	AEOD/HAGAN,D NRR/DRPM/PERB	1 1 1 1	<u>FILE CENTER 03</u> NUDOCS-ABSTRACT	2 2 1 1
EXTERNAL:	NOAC	1 1	NRC PDR	1 1

C
A
T
E
G
O
R
Y
1
D
O
C
U
M
E
N
T

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
 DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 9 ENCL 9





MAY 2 1997
L-97-124
10 CFR 50, Appendix E

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Recovery Plan and Emergency Plan Implementing Procedure


In accordance with the requirements of 10 CFR 50, Appendix E, enclosed is one copy of newly issued Emergency Plan Implementing Procedure 0-EPIP-20132, "Technical Support Center (TSC) Activation and Operation." The predecessor to this procedure was EPIP-20132. The new procedure number is 0-EPIP-20132. The primary reason for the change was to upgrade the format of the old procedure. The new procedure also includes notification forms and worksheets, additional instructions for communicators and status board keepers, and includes some editorial changes. Old procedure EPIP-20132 has been canceled. The implementation date for 0-EPIP-20132, and the cancellation date for EPIP-20132, is April 28, 1997.

Also enclosed is one copy of the Turkey Point Recovery Plan. The Recovery Plan has been rewritten as a site specific document, and now includes an Offsite Post-hurricane Checklist. Revision 1 of the Recovery Plan was reviewed and approved by the Plant Nuclear Safety Committee to ensure a formal review process. The Recovery Plan was approved on May 1, 1997, and will be reviewed yearly.

FPL has determined that the changes described do not result in a decrease in the effectiveness of the Emergency Plan.

Should there be any questions, please contact us.

Very truly yours,


R. J. Hovey
Vice President
Turkey Point Plant

A045 1/1

CLM

Enclosure

cc: Luis A Reyes, Regional Administrator, Region II, USNRC (2 copies)
T. P. Johnson, Senior Resident Inspector, USNRC, Turkey Point Plant (w/o enclosure)

9705070115 970502
PDR ADOCK 05000250
F PDR



