

SAFEGUARDS INFORMATION

EXECUTIVE SUMMARY

Turkey Point
NRC Inspection Report Nos. 50-250, 50-251/98-06

This routine, announced inspection was conducted in the area of plant support by a Regional Safeguards Specialist. The specific area evaluated was the Physical Security Program for Power Reactors.

- Procedures and lesson plans were clear in Fitness For Duty training objectives. Records reviewed reflected that the licensee was in compliance with 10 CFR 26.21(b) and implementing procedures. (Section S1.3)
- The access control program was effective in ensuring that favorably terminated individuals' badges were deactivated in accordance with the Physical Security Plan and implementing procedures. (Section S2.1)
- Compensatory posts implemented for the period of January to present for degraded protected and vital area barriers were in accordance with the Physical Security Plan. (Section S2.7)
- Security's response to the steam line break that occurred on February 16, 1998, was appropriate and a one hour notification to the NRC was not required. (Section S4.2)
- A minor change to response strategy initiated by the licensee was adequate to intercept the adversary from reaching vital equipment. (Section S4.2)
- A drill conducted by the licensee demonstrated that response officers were knowledgeable of their duties. (Section S4.2)
- The licensee's failure to protect Safeguards Information was determined to be a violation of 10 CFR 73.21(b)(xi). (Section S4.3)
- Although a reduction of training hours for Central and Secondary Alarm Station operators had occurred, the operators were qualified in accordance with the Training and Qualification Plan. (Section S5.1)
- The annual security audit was determined to be thorough, effective, and in accordance with the Physical Security Plan. (Section S7.1)

9807020251 980625
PDR ADDCK 05000250
G PDR

SAFEGUARDS INFORMATION

Document transmitted herewith
contains sensitive unclassified
information. When separated from
enclosure(s) this document is decontrolled.

