

1 EMAIL / R115

TELEPHONE REPORT

FACILITY: Shearon Harris 1

DOCKET #: 50- 400

DATE: 6/5/79

TIME:

LIC. OCC. #:

SUBJECT: Potential CDR

DESCRIPTION OF OCCURRENCE: CP&L was informed by Vendor, Tube Turns, that of 18 pipe penetrations delivered, 15 had collars which had not been heat treated after welding. The 3 which had been heat treated were 1-1/2 inch thick or greater. The others were less than 1-1/2 inch. Penetrations were for pipe sizes including 10-18 inches. Eleven penetrations not yet installed will be returned to Tube Turns immediately. Four which have been installed will be cut out and returned. Tube Turns called RII. They believe this is an isolated case and are searching records to verify. Tube Turns may submit a Part 21 report. Written report under 50.55 (e) due July 5, 1979.

SIGNATURE

A002
S 0/1

7906190348