REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8708310231 DOC.DATE: 87/08/25 NOTARIZED: NO DOCKET #
FACIL:50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400

AUTH. NAME AUTHOR AFFILIATION

COLLINS, D. M.

Region 2, Office of Director

RECIP. NAME UTLEY, E. E. RECIPIENT AFFILIATION
Carolina Power & Light Co.

SUBJECT: Forwards Insp Rept 50-400/87-30 on 870803-07 & 11. No

violations or deviations noted. Adequacy of corrective

actions to self identified violation will be examined during


future insps.

DISTRIBUTION CODE: IEO1D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3+11
TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES: Application for permit renewal filed.

05000400

•	RECIPIENT ID CODE/NAME	COPIES LTTR E		RECIPIENT ID CODE/NAME		ENCL
	PD2-1 PD	1	1	BUCKLEY, B	. 5	2
INTERNAL:	AEOD	1	1	DEDRO	1	1
	NRR MORISSEAU, D	1	1	NRR/DOEA DIR	1	1
	NRR/DREP/EPB	1	1	NRR/DREP/RPB	2	2
	NRR/DRIS DIR	1	1	NRR/PMAS/ILRB	1	1
	OE LIEBERMAN, J	1	1	OGC/HDS1	1	1
	REG FILE	1	1	RES DEPY GI	1	1
	RGN2 FILE 01	1	1			
EXTERNAL:	LPDR .	i :	1	NRC PDR	1	1
	NSIC	1	1			•



AUG 2 5 1987

Docket No. 50-400 License No. NPF-63

Carolina Power and Light Company
ATTN: Mr. E. E. Utley
Senior Executive Vice President
Power Supply and Engineering
and Construction
P. O. Box 1551
Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-400/87-30

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by A. E. Tabaka on August 3-7 and 11, 1987. The inspection included a review of activities authorized for your Shearon Harris facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified; however, your attention is brought to the self identified violation discussed in Paragraph 9 of the enclosed inspection report. We will be examining the adequacy of your corrective actions for this item during future inspections.

Your attention is invited to the unresolved item identified in the inspection report. This matter will be pursued during future inspections.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

8708310231 870825 PDR ADDCK 05000400 PDR

Should you have any questions concerning this letter, please contact us.

Sincerely,

DOUGLAS M. CC 15

Douglas M. Collins, Chief Emergency Preparedness and Radiological Protection Branch Division of Radiation Safety and Safeguards

Enclosure: Inspection Report

cc w/encl:
R. A. Watson, Vice President
 Harris Nuclear Project
D. L. Tibbitts, Director of Regulatory
 Compliance
J. L. Willis, Plant General Manager

bcc w/encl:
C. Barth, OGC
NRC Resident Inspector
A. Upchurch, Chairman, Triangle J
Council of Governments
D. Matthews, EPB/NRR
Document Control Desk
State of North Carolina

ATabaka 8/16/87 RII TDecker 8/10/87

PFredrickson 8/1/87