## FORD 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9102060089 DOC.DATE: 91/01/09 NOTARIZED: NO DOCKET # FACIL:50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400 UTH.NAME AUTHOR AFFILIATION REGION 2 (Post 820201) RECIP.NAME RECIPIENT AFFILIATION EURY, L.W. Carolina Power & Light Co.

SUBJECT: Ack receipt of 901228 response to violations noted in Insp Rept 50-400/90-21.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR | ENCL O SIZE: 2 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES: Application for permit renewal filed.

05000400

]


T

I

E

 $\mathbf{N}$ 

	RECIPIENT ID CODE/NAME PD2-1 PD	COPIES LTTR ENCL	RECIPIENT ' ID CODE/NAME BECKER, D	COPIES LTTR ENCL 1 }
INTERNAL:		2 2	AEOD AEOD/TPAB	1
, 4	AEOD/DEIIB DEDRO	i j	NRR MORISSEAU,D	i
	NRR SHANKMAN,S NRR/DOEA/OEAB	1 1	NRR/DLPQ/LPEB10 NRR/DREP/PEPB9D	1 1
	NRR/DRIS/DIR NRR/PMAS/ILRB12	1 1	NRR/DST/DIR 8E2 NUDOCS-ABSTRACT	1 1 2
	OE DIR	į Į.	OGC/HDS1	1 1
	REG FIEE 02	<b>+</b>	RGN2 FILE 01	<b>1</b>
EXTERNAL:	EG&G/BRYCE,J.H. NSIC	1 1	NRC PDR	1 1



## JAN 09 1991

Docket No. 50-400 License No. NPF-63

Carolina Power and Light Company ATTN: Mr. Lynn W. Eury Executive Vice President Power Supply P. O. Box 1551 Raleigh, NC 27602

Gentlemen:

SUBJECT: REPORT NO. 50-400/90-21

Thank you for your response of December 28, 1990 to our Notice of Violation issued on November 30, 1990, concerning activities conducted at your Harris facility. We have evaluated your responses to violations A and B, and reviewed your response to violation C, in which you did not agree with the Severity Level IV, and stated your belief that a Severity Level V was more appropriate.

We have evaluated the responses to the violations cited above, and found that the responses to violations A and B were satisfactory, and after careful review of the circumstances surrounding violation C, we concur with your assessment that this violation should be a Severity Level V instead of a Severity Level IV. This is based on the fact that failure to terminate operator licenses within 30 days upon termination of a licensed operator is not a significant safety or environmental issue. Our records will be changed accordingly.

The responses to violations A, B, and C meet the requirements of 10 CFR 2.201, and we will examine the implementation of your corrective actions during future inspections.

We appreciate your cooperation in this matter.

Sincerely,

DAVID M. VERREISE


David M. Verrelli, Chief Reactor Projects Branch 1 Division of Reactor Projects

cc: R. B. Richey, Manager Harris Nuclear Project Box 165 New Hill, NC 27562

(cc cont'd - see page 2)

9102060089 910109 PDR ADDCK 05000400 PDR TE3/

050019



(Continued) cc: C. S. Hinnant Plant General Manager Harris Nuclear Project Box 165 New Hill, NC 27562

> C. S. Olexik, Jr., Director. Regulatory Compliance Harris Nuclear Project P. 0. Box 165 New Hill, NC 27562

Richard E. Jones General Counsel Carolina Power & Light Company P. O. Box 1551 Raleigh, NC 27602

Dayne H. Brown, Director Division of Radiation Protection N. C. Department of Environment, Health & Natural Resources P. O. Box 27687 Raleigh, NC 27611-7687

bcc: Document Control Desk

G. Jenkins, 'RII T. Peebles, RII D. Verrelli, RII H. Christensen, RII R. Becker, NRR

NRC Resident Inspector U.S. Nuclear Regulatory Commission Route 1, Box 315B New Hill, NC 27562

RII: DRP HChristensen

1/ 및 /91

