| CATEGORY 1 | | | | | | | | |
|---|--|---|---|----------------------------|-----------------------|--|--|--|
| اللي ا | REGULATORY | INFORMATION | DISTRIBUTION SYSTEM | M (RIDS) | | | | |
| | 0-400 Shearon Harri AME AUTHOR A ,J. Carolina NAME RECIPIEN | is Nuclear Po AFFILIATION Power & Ligh NT AFFILIATIO | | Carolina | | | | |
| SUBJECT: Forwards 15-day special rept re SG tubes plugged as result of recent SG tube inservice insp conducted during refueling C outage number 8,per plant TS 4.4.5.5.a. | | | | | | | | |
| A DISTRIBUTION CODE: A001D COPIES RECEIVED:LTR _ ENCL _ SIZE: T TITLE: OR Submittal: General Distribution | | | | | | | | |
| NOTES: Application for permit renewal filed. | | | | | 05000400 ^E | | | |
| t | • | | b. | • | Ġ. | | | |
| | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL | RECIPIENT ID CODE/NAME | COPIES LTTR ENCI | _с О | | | |
| | PD2-1 LA FLANDERS,S | | .PD2-1 PD | 1 1 | R | | | |
| | | | | | X | | | |
| INTERNAL: | ACRS | 1 1 6 | FILE CENTER 01 | 1 1 | к У | | | |
| INTERNAL: | | | FILE_CENTER_01 NRR/DE/EMCB NRR/DSSA/SPLB NUDOCS-ABSTRACT | 1 1 1 1 1 1. 1 1. | | | | |

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 13

•

MAY

0

C

υ

Μ

Ε

'N

Т



Carolina Power & Light Company PO Box 165 New Hill NC 27562 NOV 2 3 1998 James Scarola Vice President Harris Nuclear Plant

SERIAL: HNP-98-172

United States Nuclear Regulatory Commission ATTENTION: Document Control Desk Washington, DC 20555

SHEARON HARRIS NUCLEAR POWER PLANT DOCKET NO. 50-400/LICENSE NO. NPF-63 15-DAY SPECIAL REPORT - STEAM GENERATOR TUBES PLUGGED

Déar Sir or Madam:

Pursuant to Harris Nuclear Plant Technical Specification (TS) 4.4.5.5.a, this letter submits the required 15-day special report identifying the number of steam generator tubes plugged as a result of the recent Steam Generator Tube Inservice Inspection conducted during Refueling Outage Number 8.

The complete results of the Steam Generator Tube Inservice Inspection will be submitted to the NRC within 12 months of completion as required by TS 4.4.5.5.a.

Please refer any questions regarding this submittal to Mr. J. H. Eads at (919) 362-2646.

Sincerely. lames -

2020057 PDR ADOCK

AEC/aec

Enclosure

C10102

Mr. J. B. Brady (NRC Senior Resident Inspector)
Mr. S. C. Flanders (NRR Project Manager, HNP)
Mr. L. A. Reyes (NRC Regional Administrator, Region II)

Enclosure to Serial: HNP-98-172 Page 1 of 1

SHEARON HARRIS NUCLEAR POWER PLANT DOCKET NO. 50-400/LICENSE NO. NPF-63

SPECIAL REPORT

STEAM GENERATOR TUBE INSERVICE INSPECTION (RFO8) NUMBER OF TUBES PLUGGED

| Steam Generator | A | <u>B</u> | <u>C</u> |
|---------------------------|----|----------|----------|
| Current (RFO8 only) | 39 | 15 | 18 |
| Cumulative (through RFO8) | 74 | 32 | 58 |