

MA/1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8005080287 . DOC.DATE: 80/04/30 NOTARIZED: NO DOCKET #  
FACIL:50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387  
~~50-388~~ Susquehanna Steam Electric Station, Unit 2, Pennsylv 05000388  
AUTH:NAME AUTHOR AFFILIATION  
CURTIS,N.W. Pennsylvania Power & Light Co.  
RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: Interim deficiency rept re damage sustained by  
safety-related cable during pulling activities originally  
reported 790717. Investigation in progress, Bechtel & util in  
process of finalizing agreeable plan to deal w/deficiency.

DISTRIBUTION CODE: B019B COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: SEND I&E 3 CYS FSAR & ALL AMRTS.

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	14 PM MINER	1 1	15 BC LWR #3	1 1
	20 LA LWR #3	1 1	21 AD LWR	1 1
INTERNAL:	01 REG FILE	1 1	02 NRC PDR	1 1
	05 I&E	2 2	07 EDO & STAFF	1 1
	08 MPA	1 1	09 DEPY DIR DPM	1 1
	10 QAB	1 1	11 STANDRDS DEV	1 1
	13 FIELD COOR/IE	1 1	16 AD FOR ENGR	1 1
	17 AD PLANT SYS	1 1	17 AD REAC SFTY	1 1
	22 DIR DPM	1 1	23 OELD	1 1
	AD/RCI/IE	1 1	AD/SITE TECH	1 1
	AEOD	1 1	DIRECTOR DSE	1 1
	GEOSCIENCES BR	1 1	HANAUER, S.	1 1
	I&C SYS BR	1 1	MATL ENG BR	1 1
	MECH ENG BR	1 1	POWER SYS BR	1 1
	STRUCT ENG BR	1 1		
EXTERNAL:	03 LPDR	1 1	04 NSIC	1 1
	24 ACRS	16 16		

MAY 9 1980

TOTAL NUMBER OF COPIES REQUIRED: LTTR 48 ENCL 48

**PP&L**

8005080287

5

TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101

PHONE: (215) 821-5151

NORMAN W. CURTIS  
Vice President-Engineering & Construction  
821-5381

April 30, 1980

Mr. Boyce H. Grier  
Director, Region I  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
INTERIM REPORT OF A DEFICIENCY IN  
CABLE PULLING ACTIVITIES (STATUS UPDATE)  
ERs 100450/100508 FILE 840-4/900-10  
PLA-478

References: PLA-383 dated July 17, 1979  
PLA-429 dated December 10, 1979

Dear Mr. Grier:

The damage sustained by safety related cable during pulling activities and originally reported to the NRC in our PLA-383 under the provisions of 10CFR50.55(e) remains under investigation.

Bechtel and PP&L are in the process of finalizing an agreeable plan to deal with the cable pulling deficiencies.

We will advise the Commission of other details when the plan is finalized. We expect to provide these details by August, 1980.

Very truly yours,

*N. W. Curtis/mcb*

N. W. Curtis  
Vice President-Engineering & Construction

ARS:mcb

cc: Mr. Victor Stello (15)  
Director-Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. G. McDonald, Director  
Office of Management Information & Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. Robert M. Gallo  
U.S. Nuclear Regulatory Commission  
P. O. Box 52  
Shickshinny, Pennsylvania 18655

PENNSYLVANIA POWER & LIGHT COMPANY

B019  
SE  
1/0