

MA/1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8005080287 . DOC. DATE: 80/04/30 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv 05000388
 AUTH. NAME AUTHOR AFFILIATION
 CURTIS, N.W. Pennsylvania Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: Interim deficiency rept re damage sustained by safety-related cable during pulling activities originally reported 790717. Investigation in progress, Bechtel & util in process of finalizing agreeable plan to deal w/deficiency.

DISTRIBUTION CODE: B019B COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: SEND I&E 3 CYS FSAR & ALL AMRTS.

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	14 PM MINER	1	1	15 BC LWR #3	1	1
	20 LA LWR #3	1	1	21 AD LWR	1	1
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	05 I&E	2	2	07 EDO & STAFF	1	1
	08 MPA	1	1	09 DEPY DIR DPM	1	1
	10 QAB	1	1	11 STANDRDS DEV	1	1
	13 FIELD COOR/IE	1	1	16 AD FOR ENGR	1	1
	17 AD PLANT SYS	1	1	17 AD REAC SFTY	1	1
	22 DIR DPM	1	1	23 OELD	1	1
	AD/RCI/IE	1	1	AD/SITE TECH	1	1
	AEOD	1	1	DIRECTOR DSE	1	1
	GEOSCIENCES BR	1	1	HANAUER, S.	1	1
	I&C SYS BR	1	1	MATL ENG BR	1	1
	MECH ENG BR	1	1	POWER SYS BR	1	1
	STRUCT ENG BR	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	24 ACRS	16	16			

MAY 9 1980

NORMAN W. CURTIS
Vice President-Engineering & Construction
821-5381

April 30, 1980

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION
INTERIM REPORT OF A DEFICIENCY IN
CABLE PULLING ACTIVITIES (STATUS UPDATE)
ERs 100450/100508 FILE 840-4/900-10
PLA-478

References: PLA-383 dated July 17, 1979
PLA-429 dated December 10, 1979

Dear Mr. Grier:

The damage sustained by safety related cable during pulling activities and originally reported to the NRC in our PLA-383 under the provisions of 10CFR50.55(e) remains under investigation.

Bechtel and PP&L are in the process of finalizing an agreeable plan to deal with the cable pulling deficiencies.

We will advise the Commission of other details when the plan is finalized. We expect to provide these details by August, 1980.

Very truly yours,

N. W. Curtis/mcb

N. W. Curtis
Vice President-Engineering & Construction

ARS:mcb

cc: Mr. Victor Stello (15)
Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Robert M. Gallo
U.S. Nuclear Regulatory Commission
P. O. Box 52
Shickshinny, Pennsylvania 18655

B019
SE
1/0