

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

MA/1

ACCESSION NBR: 8005080347 DOC. DATE: 80/04/30 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylva 05000387
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylva 05000388
 AUTH. NAME AUTHOR AFFILIATION
 CURTIS, N.W. Pennsylvania Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 GRIER, B.H. Region 1, Philadelphia, Office of the Director

SUBJECT: Notifies that status update of deficiencies involving PGCC cable connectors will be temporarily delayed, due to extensive evaluating process. Final report will be submitted Jul 1980.

DISTRIBUTION CODE: 80198 COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: SEND IX E 3 CYS FSAR & ALL AMDTs.

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
	14 PM MINER	1		15 BC LWR #3	1	
	20 LA LWR #3	1		21 AD LWR	1	
INTERNAL:	01 REG FILE	1		02 NRC PDR	1	
	05 I&E	2	2	07 EDO & STAFF	1	
	08 MPA	1		09 DEPY DIR OPM	1	
	10 QAB	1		11 STANDRDS DEV	1	
	13 FIELD COOR/IE	1		16 AD FOR ENGR	1	
	17 AD PLANT SYS	1		17 AD REAC SFTY	1	
	22 DIR OPM	1		23 OELD	1	
	AD/RCI/IE	1		AD/SITE TECH	1	
	AEOD	1		DIRECTOR DSE	1	
	GEOSCIENCES BR	1		HANAUER, S.	1	
	I&C SYS BR	1		MATL ENG BR	1	
	MECH ENG BR	1		POWER SYS BR	1	
	STRUCT ENG BR	1				
EXTERNAL:	03 LPDR	1		04 NSIC	1	
	24 ACRS	16	10			

Ltr
 MOORE
 EPB #2 BC
 S. BAJWA
 EPB #2 LA

MAY 9 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 52 ENCL 0
~~48~~ ~~48~~

NORMAN W. CURTIS
Vice President-Engineering & Construction
821-5381

April 30, 1980

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION
STATUS UPDATE OF DEFICIENCIES INVOLVING PGCC
CABLE CONNECTORS (MCAR 1-29)
ER 100450 FILE 840-4
PLA-477

References: PLA-437 dated 01/08/80
PLA-313 dated 01/15/79
PLA-301 dated 11/14/78

Dear Mr. Grier:

This letter serves as a supplement to our earlier correspondence on the above listed subject. Since PP&L and Bechtel Engineering are still in the process of evaluating the cause and corrective actions necessary to resolve the defective conditions, our final report on the deficiencies involving damage to cable connectors will be temporarily delayed.

We anticipate providing a final report on the subject deficiencies in July, 1980.

Very truly yours,

N.W. Curtis/s

N. W. Curtis
Vice President-Engineering & Construction

8019
SE
1/0

ARS:mcb

cc: Mr. Victor Stello (15)
Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Boyce H. Grier

- 2 -

April 30, 1980

cc: Mr. Robert M. Gallo
U. S. Nuclear Regulatory Commission
P. O. Box 52
Shickshinny, Pennsylvania 18655