

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8002140388 DOC. DATE: 80/02/05 NOTARIZED: NO DOCKET #  
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400  
 50-401 Shearon Harris Nuclear Power Plant, Unit 2, Carolina 05000401  
 50-402 Shearon Harris Nuclear Power Plant, Unit 3, Carolina 05000402  
 AUTH. NAME AUTHOR AFFILIATION  
 CHIANGI, N. J. Carolina Power & Light Co. 403  
 RECIP. NAME RECIPIENT AFFILIATION  
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director

SUBJECT: Forwards final deficiency rept re welded studs on embedded strip plates.

DISTRIBUTION CODE: B019B COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+4  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: -----

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	14 PM MINER	1	1	15 BC LWR #3	1	1
	20 LA LWR #3	1	1	21 AD LWR	1	1
INTERNAL:	01 <u>REG. FILE</u>	1	1	02 NRC PDR	1	1
	05 I&E	2	2	07 EDO & STAFF	1	1
	08 MPA	1	1	09 DEPY DIR DPM	1	1
	10 GAB	1	1	11 STANDRDS DEV	1	1
	12 JORDAN, E/IE	1	1	13 FIELD COOR/IE	1	1
	16 AD FOR ENGR	1	1	17 AD PLANT SYS	1	1
	17 AD REAC SFTY	1	1	22 DIR DPM	1	1
	23 OELD	1	1	AD/SITE TECH	1	1
	AEOD	1	1	DIRECTOR DSE	1	1
	GEOSCIENCES BR	1	1	I&C SYS BR	1	1
	MATL ENG BR	1	1	MECH ENG BR	1	1
	POWER SYS BR	1	1	S HANAUER	1	1
	STRUCT ENG BR	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	24 ACRS	16	16			

Ltr  
 MOORE  
 EPB # 2 BC  
 S. KEBLUSEK  
 EPB # 2 LA

FEB 15 1980

MA  
 1

TOTAL NUMBER OF COPIES REQUIRED: LTR 52 ENCL 48 48

002

1945  
1946

1945  
1946

1945  
1946  
1947  
1948

002

**CP&L**  
Carolina Power & Light Company  
Raleigh, N. C. 27602

COPY

February 5, 1980

Mr. James P. O'Reilly  
United States Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Northeast  
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT UNITS 1, 2, 3, AND 4  
DOCKET NOS. 50-400, 50-401, 50-402, 50-403  
DEFICIENCIES IN WELDED STUDS ON EMBEDDED STRIP PLATES  
(OPEN ITEM 400/401/79-24-01 AND 402/403/79-23/01)

Dear Mr. O'Reilly:

Attached is the final 10CFR50.55(e) report on the subject deficiency which describes the problem and the corrective action taken to accomplish resolution. With this report, Carolina Power & Light Company considers the matter closed.

If you have any questions regarding this matter, please do not hesitate to contact me.

Yours very truly,

*N. J. Chiangi types*

N. J. Chiangi - Manager  
Engineering & Construction  
Quality Assurance

KVH/bd (1201)  
Attachment

cc: ✓ Mr. V. Stello (2) W/A

8002140388

B019  
SE  
1/1

