

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8003110624 DOC. DATE: 80/02/29 NOTARIZED: NO DOCKET #
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400
 50-401 Shearon Harris Nuclear Power Plant, Unit 2, Carolina 05000401
 50-402 Shearon Harris Nuclear Power Plant, Unit 3, Carolina 05000402
 AUTH. NAME: CHIANGI, N. J. AUTHOR AFFILIATION: Carolina Power & Light Co.
 RECIP. NAME: AUTHORITY AFFILIATION: RECIPIENT AFFILIATION:

SUBJECT: Interim deficiency rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads. Estimates rept will be forwarded by 800601.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: -----

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
	14 PM MINER	1		15 BC LWR 3	1	
	20 LA LWR 3	1		21 AD LWR	1	
INTERNAL:	01 REG FILE	1		02 NRC PDR	1	
	05 I&E	2		07 EDO & STAFF	1	
	08 MPA	1		09 DEPY DIR DPM	1	
	10 QAB	1		11 STANDRDS DEV	1	
	13 FIELD COOR/IE	1		16 AD FOR ENGR	1	
	17 AD PLANT SYS	1		17 AD REAC SFTY	1	
	22 DIR DPM	1		23 OELD	1	
	AD/RCI/IE	1		AD/SITE TECH	1	
	AEOD	1		DIRECTOR DSEI	1	
	GEOSCIENCES BR	1		HANAUER, S.	1	
	I&C SYS BR	1		MATL ENG BR	1	
	MECH ENG BR	1		POWER SYS BR	1	
	STRUCT ENG BR	1				
EXTERNAL:	03 LPDR	1		04 NSIC	1	1
	24 ACRS	16	1			

MAR 14 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 48 ENCL 0

M2

Faint, illegible text at the top of the page, possibly a header or title area.

Second section of faint, illegible text, appearing as a list or series of entries.

9 9/10
9/10

9, 9/10
9/10

Vertical line of faint text or markings on the left side of the page.

Vertical line of faint text or markings in the center of the page.

Faint markings or text at the bottom center of the page.

CP&L

Carolina Power & Light Company

Raleigh, N. C. 27602

COPY

February 29, 1980

Mr. James P. O'Reilly
 United States Nuclear Regulatory Commission
 Region II
 101 Marietta Street, NW
 Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT UNITS 1, 2, 3 & 4
 DOCKET NOS. 50-400, 50-401, 50-402, 50-403
 DEFICIENCIES IN THE PROCUREMENT, FABRICATION, AND
 INSPECTION OF ENGINEERED PLATES FOR CONCRETE EMBEDMENT
 AND SUPPORT OF SAFETY RELATED LOADS - INTERIM REPORT
 (OPEN ITEM 400 & 401/79-14-01, 402 & 403/79-13-01)

Dear Mr. O'Reilly:

Per our December 27, 1979, letter on the subject deficiency, we informed you that approximately 195 plates had been reworked. Twenty plates were still on QA hold pending repair and/or NDT examination and that the the date estimated for completion of corrective action was March 1, 1980. The intent of this letter is to inform you that all corrective action has not yet been completed in that three plates still remain on QA hold pending completion of corrective action involving NDE. Engineering evaluation of several embedded plates remains to be completed. Also, final accountability for all plates needs to be resolved. It is now estimated that all corrective action will be completed by June 1, 1980, at which time the final 10CFR50.55(e) report will be submitted. We will routinely keep you appraised of our progress on this item during your site inspection visits.

If you have any questions regarding this matter, please do not hesitate to contact me.

Yours very truly,
 Original Signed By
 N. J. Chiangi
 N. J. Chiangi - Manager
 Engineering & Construction
 Quality Assurance

KVH/bwb

cc: Mr. V. Stello (2) ✓

8003110 624

B019
 5/10
 S

10000

10000

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED