

EASTERN CT CARDIOLOGY ASSOCIATES, LLC

43 West Middle Tpke, Manchester, CT 06040, Tel. 860-647-9494

TO:

USNRC, Region I Office
NMSB - Medical Licensing
2100 Renaissance Blvd, Suite 100
King of Prussia, PA 19406-2713

December 19, 2017

REC RG1 12 29 17 AM 06:04

FROM:

Rachna Khanna
Eastern CT Cardiology Associates, LLC
Mail Control No. 601412

and

Thomas I. Knox, M.D.
Hartford Cardiology Group, LLC
Mail Control No. 601413


Mr. Lester Tripp:


The following additional information is in reference to your request dated December 18, 2017, in order to continue your review of our requested amendment:

1. a. The Hartford Cardiology Group, LLC facility located at 478 Burnside Avenue, Suite 201, East Hartford, CT, will not be used by the combined practice. The East Hartford location was not put to nuclear cardiac imaging use after it was acquired and there were no radioactive sources placed at the site by the Hartford Cardiology Group.
b. The Eastern CT Cardiology Associates, LLC License No. 06-30417-01 will add the authorized location of use of 345 North Main Street, Suite 100, West Hartford. License No. 06-30417-01 ultimately becomes the sole license. Termination of License No. 06-31314-02 will be necessary.
2. Refer to the last page for the complete inventory of sealed sources that includes sources from Eastern CT Cardiology Associates and the one operating location to Hartford Cardiology Group.
3. Refer to the last page for the leakage test results of sealed sources that includes sources from Eastern CT Cardiology Associates and the one operating location to Hartford Cardiology Group.
4. The East Hartford location was not put to use after it was acquired and there were no radioactive sources placed at the site by the Hartford Cardiology Group. More recently, the West Hartford location of the Hartford Cardiology Group has resumed patient imaging; those surveys and contamination tests are current.

We appreciate your efforts with our request and we look forward to a continued safe and effective materials program. Thank you.

Respectfully submitted,


Rachna Khanna, Administrator
Eastern CT Cardiology Associates, LLC


Thomas I. Knox, MD
Hartford Cardiology Group, LLC

Hartford Cardiology Group, W. Htfd (10/02/17) sources:

| Qtr # | Source | Model | Serial # | Nom Act (uCi) | Location* | Activity (uCi)^ | Leakage (uCi) | Method |
|-------|---------------|-----------------|----------------|---------------|-----------|-----------------|---------------|--------|
| IV. | Cs-137 | SRV137-2 00U | 1333-14- 24 | 211.8 | HL | 171 | < 0.005 | AW |
| | Ba-133 | SRV133-2 50U | 1594-58- 7 | 244.4 | HL | 207 | < 0.005 | AW |
| | Co-57 fld | CTRF1377 0A | 1831-171 | 10000 | HL | 1575 | < 0.005 | AW |
| | | | | | | | | |
| | Initials: PJM | | Date: 10/02/17 | | RSO: | | | |
| | | | | | | | | |

Eastern CT Cardiology Associates (10/13/17) sources:

| Qtr # | Source | Model | Serial # | Nom Act (uCi) | Location* | Activity (uCi)^ | Leakage (uCi) | Method |
|------------|---------------|-----------------|-----------------|-------------------------|-----------|---------------------|---------------|--------|
| IV. | Ba-133 | NES-358 | S358023- 044 | 274 | HL | 74.7 | < 0.005 | AW |
| | Cs-137 | NES-356 | S356036- 006 | 222 | HL | 141.5 | < 0.005 | AW |
| [SEPT '08] | Co-57 | SRV-057- 5M | 1366-22- 17 | 5215 | HL | stored | | |
| | Co-57 fld | PF16R057 15M | 1862-180 | 15000 | HL | 3475 | < 0.005 | AW |
| | Initials: PJM | | Date: 10/13/17 | | RSO: | <i>Peter P. Mas</i> | | |
| | | | | Leak Test Date: 7/28/17 | | | | |