

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8009080254    DOC. DATE: 80/08/29    NOTARIZED: NO.    DOCKET #  
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina    05000400  
 50-401 Shearon Harris Nuclear Power Plant, Unit 2, Carolina    05000401  
 50-402 Shearon Harris Nuclear Power Plant, Unit 3, Carolina    05000402  
 50-403 Shearon Harris Nuclear Power Plant, Unit 4, Carolina    05000403  
 AUTH. NAME    AUTHOR AFFILIATION  
 CHIANGI, N.J.    Carolina Power & Light Co.  
 RECIP. NAME    RECIPIENT AFFILIATION

mal

SUBJECT: Interim deficiency rept. re procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads. Corrective action on 22 remaining plates to be completed by 801115.

DISTRIBUTION CODE: B019S    COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
ACTION:	A/D LICENSNG	04	1	YOUNGBLOOD, B	05	1
	RUSHBROOK, M.	06	1	WILSON, JERRY	07	1
INTERNAL:	AD/RCI/IE	17	1	AEOD	18	1
	ASLBP/J.HARD		1	D/DIR HUM FAC	15	1
	DIR, HUM FAC	S10	1	EDO & STAFF	19	1
	EQUIP QUAL	BR11	1	I&E	09	2
	LIC QUAL	BR 12	1	MPA	20	1
	NRC PDR	02	1	OELD	21	1
	PROC/TST REV	13	1	QA BR	14	1
<u>REG FILE</u>	01	1	RUTHERFORD, W. IE		1	
	STANDRDS DEV	21	1			
EXTERNAL:	ACRS	16	16	LPDR	03	1
	NSIC	08	1			

SEP 9 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 40 ENCL 0

R

1977  
1978  
1979  
1980  
1981  
1982  
1983  
1984  
1985  
1986  
1987  
1988  
1989  
1990  
1991  
1992  
1993  
1994  
1995  
1996  
1997  
1998  
1999  
2000  
2001  
2002  
2003  
2004  
2005  
2006  
2007  
2008  
2009  
2010  
2011  
2012  
2013  
2014  
2015  
2016  
2017  
2018  
2019  
2020  
2021  
2022  
2023  
2024  
2025

1977  
1978  
1979  
1980  
1981  
1982  
1983  
1984  
1985  
1986  
1987  
1988  
1989  
1990  
1991  
1992  
1993  
1994  
1995  
1996  
1997  
1998  
1999  
2000  
2001  
2002  
2003  
2004  
2005  
2006  
2007  
2008  
2009  
2010  
2011  
2012  
2013  
2014  
2015  
2016  
2017  
2018  
2019  
2020  
2021  
2022  
2023  
2024  
2025

1977  
1978  
1979  
1980  
1981  
1982  
1983  
1984  
1985  
1986  
1987  
1988  
1989  
1990  
1991  
1992  
1993  
1994  
1995  
1996  
1997  
1998  
1999  
2000  
2001  
2002  
2003  
2004  
2005  
2006  
2007  
2008  
2009  
2010  
2011  
2012  
2013  
2014  
2015  
2016  
2017  
2018  
2019  
2020  
2021  
2022  
2023  
2024  
2025



Carolina Power &amp; Light Company

Raleigh, N. C. 27602

COPY

File: SH N-2/18  
Item 12

August 29, 1980

Mr. James P. O'Reilly  
United States Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Northwest  
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT  
UNITS 1, 2, 3, AND 4  
DEFICIENCIES IN THE PROCUREMENT,  
FABRICATION AND INSPECTION OF  
ENGINEERED PLATES FOR CONCRETE EMBEDMENT  
AND SUPPORT OF SAFETY RELATED  
LOADS - INTERIM REPORT  
OPEN ITEM 400 AND 401/79-14-01, 402 AND 403/79-13-01

Dear Mr. O'Reilly:

Per our May 30, 1980, interim report on the subject deficiency, we informed you that out of the 469 defective plates identified, 22 plates still required some form of corrective action and it was estimated that the corrective action completion date was September 1, 1980. The intent of this letter is to inform you that corrective action on the 22 remaining plates has not yet been completed. Tests specified by the Architect Engineer are presently being conducted to determine the acceptability of the plates. Depending on the acceptability of the test results, it is now estimated that all corrective action will be completed by November 15, 1980, at which time the final 10CFR50.55(e) report will be submitted.

If you have any questions regarding this matter, please do not hesitate to contact me.

NJC/mt (5061)

cc: Mr. V. Stello (2) ✓

Yours very truly,

Original Signed By

N. J. Chiangi

N. J. Chiangi - Manager  
Engineering & Construction  
Quality Assurance

B019  
S 1/0

8009080254

5

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000



Carolina Power &amp; Light Company

Raleigh, N. C. 27602

COPY

File: SH N-2/18  
Item 12

August 29, 1980

Mr. James P. O'Reilly  
United States Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Northwest  
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT  
UNITS 1, 2, 3, AND 4  
DEFICIENCIES IN THE PROCUREMENT,  
FABRICATION AND INSPECTION OF  
ENGINEERED PLATES FOR CONCRETE EMBEDMENT  
AND SUPPORT OF SAFETY RELATED  
LOADS - INTERIM REPORT  
OPEN ITEM 400 AND 401/79-14-01, 402 AND 403/79-13-01

Dear Mr. O'Reilly:

Per our May 30, 1980, interim report on the subject deficiency; we informed you that out of the 469 defective plates identified, 22 plates still required some form of corrective action and it was estimated that the corrective action completion date was September 1, 1980. The intent of this letter is to inform you that corrective action on the 22 remaining plates has not yet been completed. Tests specified by the Architect Engineer are presently being conducted to determine the acceptability of the plates. Depending on the acceptability of the test results, it is now estimated that all corrective action will be completed by November 15, 1980, at which time the final 10CFR50.55(e) report will be submitted.

If you have any questions regarding this matter, please do not hesitate to contact me.

NJC/mt (5061)

cc: Mr. V. Stello (2) ✓

Yours very truly,

Original Signed By

N. J. Chiangi

N. J. Chiangi - Manager  
Engineering & Construction  
Quality Assurance