

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:
Mr. James P. O'Reilly

FROM:
Niagara Mohawk Power Corp.
Syracuse, New York
J. Bartlett

DATE OF DOCUMENT:
5/10/77

DATE RECEIVED
5/16/77

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
1516250

DESCRIPTION

Ltr. trans the following:

PLANT NAME:
Nine Mile Point Unit No. 1 (1-P)

RJL

ENCLOSURE

Licensee Event Report (RO 50-220/77-19 & 77-20) on 4/27/77 concerning two containment oxygen sampling system check valves indicating leakage in excess of the single valve criteria in Tech. Specs.....

ACKNOWLEDGED
DO NOT REMOVE

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:	<i>Leak</i>
W/3 CYS FOR ACTION	
LIC. ASST.:	<i>Pavish</i>
W/1 CYS	
ACRS	<i>16 CYS HOLDING/SENT As CAT B</i>

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE	
<input type="checkbox"/> NRC PDR	
<input type="checkbox"/> I & E (2)	
<input type="checkbox"/> MIPC	
<input type="checkbox"/> SCHROEDER/IPPOLITO	
<input type="checkbox"/> HOUSTON	
<input type="checkbox"/> NOVAK/CHECK	
<input type="checkbox"/> GRIMES	
<input type="checkbox"/> CASE	
<input type="checkbox"/> BUTLER	
<input type="checkbox"/> HANAUER	
<input type="checkbox"/> TEDESCO/MACCARY	
<input type="checkbox"/> EISENHUT	
<input type="checkbox"/> BAER	
<input type="checkbox"/> SHAO	
<input type="checkbox"/> VOLLMER/BUNCH	
<input type="checkbox"/> KREGER/J. COLLINS	

EXTERNAL DISTRIBUTION

LPDR: <i>Dswesol, NY</i>	
TIC:	
NSIC:	

CONTROL NUMBER

771360237

11.11.11

11.11.11

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

Regulatory


File Copy

May 10, 1977

Mr. James P. O'Reilly
 Director
 United States Nuclear Regulatory Commission
 Region I
 631 Park Avenue
 King of Prussia, PA. 19406

RE: Docket No. 50-220


Dear Mr. O'Reilly:



In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification, we hereby submit Licensee Event Reports, LER 77-19 and LER 77-20.

These reports were completed in the format designated in the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 2974, revised December 8, 1975.

Very truly yours,



J. Bartlett
 Executive Vice President
 for R.R. Schneider
 Vice President -
 Electric Production

MAS/mtm

Enc.

771360237

11/11/11

11/11/11

RECEIVED
U. S. N. R. C.
MAY 13 1977
OF PRUSSIA DT

1977 MAY 16 AM 11 51

RECEIVED DOCUMENT
PROCESSING UNIT

NIAGARA MOHAWK POWER CORPORATION

TELECOPY MESSAGE

TO: 515-347-1151 (24) FROM: 515-343-2110 (1376) DATE/TIME 5/09/77
 Telephone Number Telephone Number

TO: James P. O'Reilly Director of Regulatory Operation
 USNRC Region I
 631 Park Avenue
 King of Prussia, Pa. 19406

From: Niagara Mohawk Power Corporation
 Nine Mile Point Nuclear Station
 Unit #1
 P.O. Box #32
 Lycoming, New York 13093

SUBJECT: PROMPT REPORTABLE OCCURRENCE
 DOCKET NO. 50-220 LICENSE NO. DPR-63
 ASSIGNED LER NO. XXX 76-45

EVENT DATE: 12/76 REPORT DATE: 5/9/77

EVENT DESCRIPTION: During a review of chemical discharge records, it was discovered that the sodium limiting value for liquid effluents was exceeded (1.59 ppm vs limit of 1.5 ppm - see Environmental Technical Specifications 2.3-1)

COMPONENTS INVOLVED: None

CAUSE AND REMEDIAL ACTION: The surveillance procedure was revised to assure a more timely check on the concentration of discharges which have been made. A station modification to provide discharge throttling capability will prevent re-occurrence.

FACILITY STATUS:


THERMAL INT _____

- c) Routine Startup _____
- d) Routine Shutdown _____
- e) Steady State Oper _____
- f) Load Change _____

- g) Shutdown _____
- h) Refueling _____
- i) Other _____
- j) Not Applicable

A written follow-up report will be sent within two weeks.

TELECOPY TO J.P. O'Reilly FROM T.J. Pez King DATE 5/09/77
 NAME NAME



TELECOPY MESSAGE

TO: 215-337-1550 (324) FROM: 315 342-2110 DATE/TIME 5/09/77
Telephone Number Telephone Number

TO: James P. O'Reilly Director of Regulatory Operation
OSMRC Region I
631 Park Avenue
King of Prussia, PA. 19406
From: Niagara Mohawk Power Corporation
Nine Mile Point Nuclear Station
Unit #1
P.O. Box #32
Lycoming, New York 13093

SUBJECT: PROMPT REPORTABLE OCCURRENCE
DOCKET NO. 50-220 LICENSE NO. DPR-63
ASSIGNED LER NO. 77- 21

EVENT DATE: 5/7/77 REPORT DATE: 5/9/77

EVENT DESCRIPTION: Failure to continuously monitor stack gross radioactivity as indicated in Environmental Technical Specifications 2.4.4.B.

COMPONENTS INVOLVED: Stack Sample Pump

CAUSE AND REMEDIAL ACTION: Stack sample pump was out of service for 9 hours and 20 minutes due to blown fuse. Fuse was replaced and pump was returned to service.

FACILITY STATUS: % THERMAL IN 0
c) Routine Startup _____ g) Shutdown _____
d) Routine Shutdown _____ h) Refueling _____
e) Steady State Oper _____ i) Other _____
f) Load Change _____ j) Not Applicable _____

A written follow-up report will be sent within two weeks.

TELECOPY TO J P O'Reilly FROM T J F. King DATE 5/09/77
MAIL MAIL





11