official

## FEB 08 1990

Docket No. 50-400 License No. NPF-63

Carolina Power and Light Company ATTN: Mr. Lynn W. Eury Executive Vice President Power Supply P. O. Box 1551 Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-400/89-33

The NRC Systematic Assessment of Licensee Performance (SALP) has been completed for your Shearon Harris facility. The facility was evaluated for the period July 1, 1988 through November 30, 1989. The results of the evaluation are documented in the enclosed Initial SALP Report. This report will be discussed with you at a public meeting to be held at the Harris Energy and Environmental Center on February 20, 1990, at 1:00 p.m.

The performance of your Shearon Harris facility was evaluated in the functional areas of Plant Operations, Radiological Controls, Maintenence/Surveillance, Emergency Preparedness, Security, Engineering/Technical Support, and Safety Assessment/Quality Verification. Although the functional areas evaluated during this assessment period are not identical to those evaluated in the previous period, a close correlation can be made for identifying changes in performance.

The assessment indicates significant progress has been made in five of the seven functional areas and that a superior level of performance has been achieved. We commend you and your staff on such a significant achievement.

However, the assessment presents an enigma in that each of the functional areas that had been rated as superior performance in the previous SALP period have declined and all other areas have advanced in performance. The perception created is that management has so focussed on those areas previously assessed as less than superior that they have neglected to provide sufficient oversight to maintain a superior performance in the functional areas of Maintenance/Surveillance and Security. The assessment narrative clearly indicates the need for attention to detail and management involvement in these two areas and the SALP board has specifically recommended increased emphasis on this.

Any comments you have concerning our evaluation of the performance of your Shearon Harris facility should be submitted to this office within 30 days following the date of our meeting. These comments will be considered in the development of the Final SALP Report. Your comments and a summary of our meeting will be issued as an appendix to the Final SALP Report.



9002260306 900208 PDR ADOCK 05000400 @ PDC

IF4 11



## v

٠

.



k



## Carolina Power and Light Company

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

(Original signed by SDEbneter) Stewart D. Ebneter Regional Administrator

Enclosure: Initial SALP Report - Shearon Harris

cc w/encl: R. B. Richey, Manager Harris Nuclear Project Box 165 New Hill, NC 27562

C. S. Hinnant Plant General Manager Harris Nuclear Project Box 165 New Hill, NC 27562

D. L. Tibbitts, Director Regulatory Compliance Harris Nuclear Project P. O. Box 165 New Hill, NC 27562

Richard E. Jones General Counsel Carolina Power & Light Company P. O. Box 1551 Raleigh, NC 27602

Dayne H. Brown, Director Division of Radiation Protection N. C. Department of Environment, Health & Natural Resources P. O. Box 27687 Raleigh, NC 27611-7687

State of North Carolina

bcc w/encl: (See page 3)




2

Carolina Power and Light Company

FEB 08 1990

bcc w/encls: K. M. Carr, Chairman T. M. Roberts, Commissioner K. C. Rogers, Commissioner J. R. Curtiss, Commissioner F. J. Remick, Commissioner J. M. Taylor, EDO H. L. Thompson, Jr., EDO R. W. Borchardt, Regional Coordinator, EDO T. E. Murley, NRR S. Varga, NRR E. G. Ädensam, NRR R. A. Becker, NRR R. Nease, SALP Coordinator, NRR Regional Administrators, RI, RIII RIV, and RV K. Clark, RII, PAO D. M. Verrelli, DRP, RII H. C. Dance, DRP, RII R. E. Carroll, DRP, RII K. Landis, Chief, TSS NRC Resident Inspector DRS and DRSS Branch Chiefs, and Section Chiefs **INPO** IMPELL Document Control Desk



3



τ.

·

•