

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

716 Edney Building

May 7, 1979

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE
REPORT BPRO-50-260/794

The enclosed report provides details concerning the reactor building,
turbine building, and refueling zone vent exhaust monitor, RM-90-250,
that failed surveillance test SI 4.8.B-4.3, section 4e during normal
operation. This report is submitted in accordance with Browns Ferry
unit 2 Technical Specification 6.7.2.b(a).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)

Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

R. F. Sullivan, NRC Inspector, Browns Ferry

7905110 3/3

1002
5/11

THE UNITED STATES OF AMERICA

DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D. C. 20535

MEMORANDUM FOR THE DIRECTOR

SUBJECT: [Illegible text]

[Illegible text]

Very truly yours,

[Illegible signature]

Director of FBI

(S) [Illegible]

(U) [Illegible]

[Illegible text]

(U) [Illegible]

[Illegible text]

[Illegible text]

11