

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

716 Edney Building

December 21, 1979

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFRO-50-296/7921

The enclosed report provides details concerning the differential pressure between the drywell and pressure suppression chamber which could not be maintained at greater than 1.3 psig with unit 3 at 200 MWe following unit return to service following refueling outage. This report is submitted in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.a.3.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

R. F. Sullivan, NRC Inspector, Browns Ferry

A002
S
//

UNITED STATES DEPARTMENT OF JUSTICE

FEDERAL BUREAU OF INVESTIGATION

Washington, D. C.

October 10, 1954

Mr. J. Edgar Hoover
Director
Federal Bureau of Investigation
Washington, D. C.

Dear Mr. Hoover:

I have the honor to acknowledge the receipt of your letter of October 7, 1954, regarding the matter mentioned therein. The Bureau is currently reviewing the information provided and will advise you of the results of our investigation as soon as possible.

Sincerely,
Special Agent in Charge

Very truly yours,
Special Agent in Charge

cc: Mr. Tolson

cc: Mr. Clegg

cc: Mr. Glavin

cc: Mr. Ladd
cc: Mr. Nichols
cc: Mr. Rosen
cc: Mr. Tracy

cc: Mr. Harbo

cc: Mr. Mohr
cc: Mr. Winterrowd

cc: Mr. Nease

cc: Mr. Gurnea

100-100000-100

October 10, 1954

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

716 Edney Building

December 21, 1979

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFRO-50-296/7921

The enclosed report provides details concerning the differential pressure between the drywell and pressure suppression chamber which could not be maintained at greater than 1.3 psig with unit 3 at 200 MWe following unit return to service following refueling outage. This report is submitted in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.a.3.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

R. F. Sullivan, NRC Inspector, Browns Ferry

A002
S
//

79122 80 503

