

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

716 Edney Building

JAN 15 1980

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFR0-50-296/7927

The enclosed report provides a detailed description of the following
nonconservative setpoints found during the performance of Surveillance
Instruction 4.2.C-1A. The APRM "B" high flux trip was found greater than
120 percent and the APRM "D" inoperative rod block and alarm trip was
found less than 13 LPRM inputs. This report is submitted in accordance
with Browns Ferry unit 3 Technical Specification 6.7.2.b(1).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallec
Nuclear Safety Analysis Center
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

8001210197

A002
S
1/1

THE NATIONAL ARCHIVES

COLLECTIONS

1964

1964

1964