

**TENNESSEE VALLEY AUTHORITY**

CHATTANOOGA, TENNESSEE 37401  
716 Edney Building

**JAN 18 1980**

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET  
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE  
REPORT BFRO-50-260/802

The enclosed report provides details concerning flow control valve  
2-FCV-68-79 on the recirculation system which would not operate with  
unit 2 in cold shutdown. This report is submitted in accordance with  
Browns Ferry unit 2 Technical Specification 6.7.2.b.2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)

Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

A002  
S  
///

TELETYPE UNIT

COMMUNICATIONS SECTION

WASHINGTON, D.C.

1954 JAN 10

TO DIRECTOR  
FROM SAC, NEW YORK  
RE: [Illegible]

URGENT

RE: [Illegible]

[Illegible text]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible text]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Handwritten notes]

[Handwritten notes]