

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

716 Edney Building

FEB 8 1980

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFRO-50-296/802

The enclosed report provides details concerning residual heat removal
system flow control valve FCV-74-73 which tripped in mid-position
while performing Surveillance Instruction 4.5.B.1.d on unit 3. This
report is submitted in accordance with Browns Ferry unit 3 Technical
Specification 6.7.2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavalley
Nuclear Safety Analysis Center
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

A002
S
1/1
548
507

80 02140

UNITED STATES GOVERNMENT

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

1981 8 14

MEMORANDUM FOR THE DIRECTOR, BUREAU OF LAND MANAGEMENT
FROM: [Illegible]
SUBJECT: [Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

(S) [Illegible]

[Illegible]

[Illegible]

(S) [Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Handwritten notes]

[Handwritten notes]

[Handwritten notes]

[Handwritten notes]