

**TENNESSEE VALLEY AUTHORITY**

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

June 2, 1980

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET  
NO. 50-296 - FACILITY OPERATING LICENSE DPR-63 - REPORTABLE OCCURRENCE  
REPORT BWRO-50-296/8017

The enclosed report provided details concerning nonperformance of the  
last page of the Surveillance Instruction 4.11.C, 3 and 4 which was  
discovered missing. This report is submitted in accordance with Browns  
Ferry Technical Specification 6.7.2.b(3).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

A002  
5/11

8006060309

S

An Equal Opportunity Employer



Faint, illegible text at the top of the page, possibly a header or title.

JA 2

4/20/71

7

105-800008