

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 81025 Technical Specification Involved Table 3.2.B

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 5/18/81 Time of Occurrence 0930 Unit 3

Identification and Description of Occurrence:

3-LS-73-57B failed to operate

Conditions Prior to Occurrence:

Unit 1 refueling outage

Unit 2 at 98%

Unit 3 at 99%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Met surveillance requirements of table 3:2.B

Apparent Cause of Occurrence:

Stuck float chamber in switch 3-LS-73-57B

Analysis of Occurrence:

There were no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Flushed switch float chamber, returned switch to service, and successfully performed SI 4.2.B-27.

Failure Data:

BFRO-50-259/80051; 260/80052, 81001; 296/81012

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: _____

JUL 20 1981

REACTOR FACILITY FEE DETERMINATION

PRELIMINARY

FINAL

AMENDED

INSTRUCTIONS. Fill-in items 1 through 14, as applicable, and send the original copy to the License Fee Management Branch.

2. DOCKET NUMBER(S)

50-296

3. ACCESSION NUMBER

4. LICENSEE

Tennessee Valley Authority

5. PLANT NAME AND UNIT(S)

Browns Ferry 3

6. DATE OF APPLICATION

4/9/81

7. FEE REMITTED

YES
 NO

8. LICENSEE FEE DETERMINATION

CLASS I	CLASS II	CLASS III	CLASS IV	CLASS V	CLASS VI	EXEMPT	NONE

9. SUBJECT

BCWR Screen Discharge System - Extension of Implementation Date requested in 4/9/81 Order

10. TAC NUMBER ASSIGNED (if available)

11. APPROVAL

DATE OF ISSUANCE

LETTER ORDER

4/10/81

AMENDMENT NUMBER(S)

12. NRC FEE DETERMINATION

The above application has been reviewed in accordance with Section 170.22 of Part 170 and is properly categorized.

The above application has been reviewed in accordance with Section 170.22 of Part 170 and is incorrectly classified.

Fee should be class(es):

JUSTIFICATION FOR CLASSIFICATION OR RECLASSIFICATION.

This application is a Class II type of action and is exempt from fees because it is:

Filed by a nonprofit educational institution.

Filed by a Government agency and is not for a power reactor.

For a Class I, II, or III amendment which results from an NRC request dated 1/9/81 for the application and the amendment is to simply or clarify License or Technical Specifications; has only minor safety significance; and is being issued for the convenience of NRC (must meet all of the criteria).

Other (State reason therefor)

RECEIVED BY LFMB
 DATE 6/23/81
 BY A.M.
 BY A.L.B.
 ACTION CENTER

memo 4

13. SIGNATURE (Branch Chief)

Joe Spalato

DATE

6/17/81

14. FINAL CERTIFICATION: The preliminary fee determination has been reassessed and is hereby affirmed.

SIGNATURE (Project Manager or Branch Chief)

DATE

FOR LICENSE FEE MANAGEMENT BRANCH USE ONLY (All others do not write below this line)

The above exemption request has been reviewed and is hereby accepted as being exempt

SIGNATURE (Chief, LFMB)

W. O. Miller

DATE

7/13/81

DISTRIBUTION BY LFMB

Records Services Branch

DL Branch Chief

LFMB Exemption File

LFMB Reactor File

Docket 50-296

47. 1 5 1981