

CORRECTION TO LICENSE AMENDMENT NO. 108

FACILITY OPERATING LICENSE NO. DPR-33

DOCKET NO. 50-259

Remove the following page and replace with an identically numbered page.

255

8410110016 840919
PDR ADOCK 05000259
P PDR



r

1994

Group 7: The valves in Group 7 are automatically actuated by only the following condition:

1. The respective turbine steam supply valve not fully closed.

Group 8: The valves in Group 8 are automatically actuated by only the following condition:

1. High Drywell pressure
2. Reactor vessel low water level (538")



CORRECTION TO LICENSE AMENDMENT NO. 102

FACILITY OPERATING LICENSE NO. DPR-52

DOCKET NO. 50-260

Remove the following page and replace with an identically numbered page.

255

Group 7: The valves in Group 7 are automatically actuated by only the following condition:

1. The respective turbine steam supply valve not fully closed.

Group 8: The valves in Group 8 are automatically actuated by only the following condition:

1. High Drywell pressure
2. Reactor vessel low water level (538")

CORRECTION TO LICENSE AMENDMENT NO. 75

FACILITY OPERATING LICENSE NO. DPR-68

DOCKET NO. 50-296

Remove the following page and replace with an identically numbered page.

267

only the following condition:

1. The respective turbine steam supply valve not fully closed.

Group 8: The valves in Group 8 are automatically actuated by only the following condition:

1. High Drywell Pressure
2. Reactor vessel low water level (538")

