

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

MM1

ACCESSION NBR: 8007140170      DCC DATE: 80/07/08      NOTARIZED: NO      DOCKET #  
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv      05000387  
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv      05000388  
 AUTH. NAME      AUTHOR AFFILIATION  
 CURTIS, N.W.      Pennsylvania Power & Light Co.  
 RECIP. NAME      RECIPIENT AFFILIATION  
 GRIER, B.H.      Region 1, Philadelphia, Office of the Director

SUBJECT: Forwards final deficiency rept re insulation damage & deficient pin crimps in power generation control complex/ advanced control room panel connectors.

DISTRIBUTION CODE: B019S      COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+2  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: Send I & E 3 Copies FSAR & All Amends

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
ACTION:	AD <u>Licensing</u> 21	1	1	BC <u>Youngblood, B.</u> 15	1	1
	LA <u>Rushbrook, M.</u> 20	1	1	PM <u>Stark, P.</u> 14	1	1
INTERNAL:	AD/RCI/IE	1	1	AEOD	1	1
	DIR, HUM FAC SFY	1	1	EDO & STAFF 07	1	1
	EQUIP QUAL BR16	1	1	FIELD COOR/IE13	1	1
	HYD/GEO BR 22	1	1	I&E 05	2	2
	LIC QUAL BR	1	1	MOORE, V.	1	1
	MPA 08	1	1	NRC PDR 02	1	1
	OELD 23	1	1	OR ASSESS BR 17	1	1
	PROC/TEST/REV BR	1	1	QA BR 10	1	1
	<u>REG FILE</u> 01	1	1	STANDRDS DEV 11	1	1
	EXTERNAL: ACRS 24	16	16	LPDR 03	1	1
NSIC 04	1	1				

JUL 15 1980



TOTAL NUMBER OF COPIES REQUIRED: LTR 44 ENCL 44

**PP&L**

TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101      PHONE: (215) 821-5151

NORMAN W. CURTIS  
Vice President-Engineering & Construction  
821-5381

July 8, 1980

80-75  
50 3:15

Mr. Boyce H. Grier  
Director, Region I  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
FINAL REPORT OF A DEFICIENCY ON PGCC/ACR  
ELECTRICAL CONNECTORS  
ERS 100450/100508      FILE 840-4/900-10  
PLA-506

Reference: PLA-447 dated 2/1/80

Dear Mr. Grier:

This letter serves to provide the Commission with a final report of a deficiency on Power Generation Control Complex/Advanced Control Room (PGCC/ACR) panel connectors originally reported in the referenced letter. The information is furnished in fulfillment of our obligations under the provisions of 10CFR50.55(e).

The attachment to this letter describes the deficient condition along with its safety implications and the corrective action being taken to achieve resolution.

We trust the Commission will find the information forwarded by this letter to be satisfactory.

Very truly yours,



N. W. Curtis  
Vice President-Engineering & Construction-Nuclear

Attachment

ARS:jmk

B019  
S  
1/1

8007140170

July 8, 1980

cc: Mr. Victor Stello (15)  
Director-Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. G. McDonald, Director  
Office of Management Information & Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. Robert M. Gallo  
U. S. Nuclear Regulatory Commission  
P.O. Box 52  
Shickshinny, Pennsylvania 18655