

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NO: 8012250337 DOC. DATE: 80/11/16 NOTARIZED: NO
 FACILITY: 50-317 Susquehanna Steam Electric Station, Unit 1, Pennsylvania
 50-399 Susquehanna Steam Electric Station, Unit 2, Pennsylvania
 AUTH. NAME: UNKNOWN AFFILIATION
 CURTIS, W. G. Pennsylvania Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION
 GRIER, B. H. Region 1, Philadelphia, Office of the Director

DOCKET #
~~0500387~~
 0500388

ma/1

SUBJECT: Interim deficiency report re application of non-0 pilot solenoid valves in safety-related sys. Final report delayed until Feb 1981.

DISTRIBUTION CODE: 80195 COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: Send I&E 3 copies PS&K & all amends.
 Send ISF 3 copies PS&K & all amends.

05000387
 05000388


	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	A/O LICENSING 04	1 1	YOUNG&LOOC, B 05	1 1
	REGISTRATION 06	1 1	STARK, R. 07	1 1
INTERNAL:	AD/ACT/IE 17	1 1	GEN 18	1 1
	ASLBI/J. H. AND	1 1	D/DIR NUM FAC 15	1 1
	LIC, DIV OF LIC	1 1	EDD & STAFF 19	1 1
	EQUIP QUAL BR 11	1 1	HYD/GEO GR 22	1 1
	I&E 07	1 1	LIC QUAL SR 12	1 1
	ISF 20	1 1	INC PLR 02	1 1
	DELD 21	1 1	PLANT/ST REV 13	1 1
	GA GR 14	1 1	REG FILE 01	1 1
	ROTHERFORD, W. IC	1 1	STANDARDS DEV 21	1 1
	EXTERNAL:	ACKS 10	10 10	LPDR 03
	NSIC 00	1 1		

DEC 24 1980

40 40

TOTAL NUMBER OF COPIES REQUIRED: LTR ENCL 40

A



PP&L

TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101 PHONE: (215) 821-5151

NORMAN W. CURTIS
Vice President - Engineering & Construction - Nuclear
821-5381

December 16, 1980

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION
STATUS UPDATE ON DEFICIENCY RELATING TO
IMPROPER SAFETY CLASSIFICATION FOR SOLENOID VALVES
ERs 100450/100508 FILES 840-4/900-10
PLA-588

Reference: PLA-515 dated 07/23/80
PLA-483 dated 05/13/80

Dear Mr. Grier:

This letter serves to supplement the above referenced correspondence which advised the Commission of a deficiency relating to application of non-Q pilot solenoid valves in safety related systems.

PP&L is awaiting additional information regarding the factors which may have contributed to the condition. Based upon the projected receipt of said information, we expect our final report, required under the provisions of 10CFR50.55(e), to be delayed until February, 1981.

Very truly yours,



N. W. Curtis
Vice President-Engineering & Construction-Nuclear

FLW:mcb

cc: Mr. Victor Stello (15)
Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

B019
S
1/1

8012230 337 PENNSYLVANIA POWER & LIGHT COMPANY
S

US NRC
DISTRIBUTION SERVICES
BRANCH

1980 DEC 22 PM 12 43

RECEIVED DISTRIBUTION
SERVICES UNIT

Mr. Boyce H. Grier

- 2 -

December 16, 1980

cc: Mr. Robert M. Gallo
U. S. Nuclear Regulatory Commission
P. O. Box 52
Shickshinny, Pennsylvania 18655

