

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8103100443 DUC. DATE: 81/03/06 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv 05000388
 AUTH. NAME AUTHOR AFFILIATION
 CURTIS, N.W. Pennsylvania Power & Light Co.
 RECIPIENT NAME RECIPIENT AFFILIATION
 GRIER, B.H. Region 1, Philadelphia, Office of the Director

SUBJECT: Interim deficiency rept re pipe supports welded to
 containment liner plate, initially reported on 810529.
 Resolution of deficiency is more complex than originally
 anticipated. Final rept in May 1981.

DISTRIBUTION CODE: 8019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: Send I&E 3 copies FSAR & all amends. 05000387
 Send I&E 3 copies FSAR & all amends. 05000388

ACTION:	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME		LTR	ENCL
ACTION:	A/D LICENSNG 04		1	1	YOUNGBLOOD, B 05		1	1
	RUSHBROOK, M. 06		1	1	STARK, R. 07		1	1
INTERNAL:	AD/RCI/IE 17		1	1	ASLBP/J. HARD		1	1
	D/DIR HUM FAC15		1	1	EDO & STAFF 19		1	1
	EQUIP QUAL BR11		1	1	HYD/GEO BR 22		1	1
	I&E 09		1	1	LIC QUAL BR 12		1	1
	MPA 20		1	1	NRC PDR 02		1	1
	OELD 21		1	1	PROG/TST REV 13		1	1
	QA BR 14		1	1	REG FILE 01		1	1
	RUIHERFORD, W. IE		1	1	STANDARDS DEV 21		1	1
EXTERNAL:	ACRS 16		16	16	LPDR 03		1	1
	NSIC 08		1	1				

MAR 12 1981

TOTAL NUMBER OF COPIES REQUIRED: LTR 38 ENCL 38

MA
 JF


PP&L

TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101 PHONE: (215) 770-5151

NORMAN W. CURTIS
Vice President-Engineering & Construction-Nuclear
770-5381

March 6, 1981

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406



SUSQUEHANNA STEAM ELECTRIC STATION
STATUS UPDATE OF A DEFICIENCY RELATING TO
PIPE SUPPORTS WELDED TO CONTAINMENT LINER PLATE
ERs 100450/100508 FILES 840-4/900-10
PLA-653

Reference: PLA-489 dated 5/29/81

Dear Mr. Grier:

This letter serves to supplement the above referenced correspondence which advised the Commission of a deficiency involving pipe supports welded to the containment liner plate.

Bechtel Engineering has advised PP&L that the resolution of this subject has been determined to be more complex than originally anticipated. We now estimate that a final report, pursuant to the requirements of 10 CFR 50.55(e), will be available in May, 1981.

Very truly yours,

N. W. Curtis
Vice President-Engineering & Construction-Nuclear

FLW:sab

B019
5
1/1

5
8103100443

Mr. Boyce H. Grier

- 2 -

March 6, 1981

cc: Mr. Victor Stello (15)
Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director (1)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Robert M. Gallo
U. S. Nuclear Regulatory Commission
P. O. Box 52
Shickshinny, PA 18655