

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8104280282 DUC DATE: 81/04/20 NOTARIZED: NO DOCKET #  
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387  
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv 05000388  
 AUTH. NAME AUTHOR AFFILIATION  
 CURTIS, N.W. Pennsylvania Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 YOUNGBLOOD, B.J. Licensing Branch 1

SUBJECT: Withdraws previous response to IE Bulletin 80-06 that all associated safety-related equipment remains in emergency mode except for circuits identified in response to TMI Action Plan Item 11.E.4.2. Answer will be in 810530 response.

DISTRIBUTION CODE: 9001S COPIES RECEIVED: LTR 1 ENCL 2 SIZE: 1  
 TITLE: PSAR/FSAR AMDTS and Related Correspondence

NOTES: Send I&E 3 copies FSAR & all amends. 05000387  
 Send I&E 3 copies FSAR & all amends. 05000388

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
ACTION:	A/D LICENSNG	1		LIC BR #2 BC	1	
	RUSHBROOK, M.	1		STARK, R. 04	1	
INTERNAL:	ACCID EVAL BR26	1		AUX SYS BR 07	1	
	CHEM ENG BR 08	1		CONT SYS BR 09	1	
	CORE PERF BR 10	1		EFF TR SYS BR12	1	
	EMERG PREP 22	1		EQUIP QUAL BR13	3	
	GEOSCIENCES 14	1		HUM FACT ENG BR	1	
	HYD/GEO BR 15	2		I&C SYS BR 16	1	
	I&E 06	3		LIC GUID BR	1	
	LIC QUAL BR	1		MATL ENG BR 17	1	
	MECH ENG BR 18	1		MPA	1	
	NRG PDR 02	1		OELD	1	
	OP LIC BR	1		POWER SYS BR 19	1	
	PRUC/TST REV 20	1		QA BR 21	1	
	RAU ASSESS BR22	1		REAC SYS BR 23	1	
	REG FILE 01	1		SIT ANAL BR 24	1	
STRUCT ENG BR25	1					
EXTERNAL:	ACRS 27	16	1	LPDR 03	1	
	NSIC 05	1				

APR 21 1981

AO 2

TOTAL NUMBER OF COPIES REQUIRED: LTR 56 ENCL 2

2

PD

**PP&L**

TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101      PHONE: (215) 821-5151

APR 20 1981



Mr. B.J. Youngblood  
Licensing Branch 1  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
ESF REQUEST                                      FILE 841-2  
ER100450  
PLA-684

DOCKET NOS. 50-387 & 50-388

Dear Mr. Youngblood:

In PLA-684 we advised you that, upon the reset of an ESF actuation signal, all associated safety-related equipment remains in the emergency mode except for circuits identified in response to TMI item II.E.4.2. Upon further review we have concluded that this was a premature response. The question of ESF equipment reset is addressed by IE Bulletin 80-06 for which we project a response by 5/30/81. Since the technical reviews necessary to respond to Bulletin 80-06 have not been completed we must withdraw the information presented in PLA-684.

The answer to your concern will appear in our response to Bulletin 80-06.

Very truly yours,

A handwritten signature in cursive script that reads "N.W. Curtis".

N.W. Curtis  
Vice President-Engineering and Construction-Nuclear

JAB/nar

cc:

R.M. Stark

bcc:

N.W. Curtis  
W.E. Barberich  
B.A. Snapp  
C.T. Coddington  
R.J. Shovlin

A

Boo1  
S 1/0

8104280 282