

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

MAI

ACCESSION NBR: 8007250487 DOC. DATE: 80/07/21 NOTARIZED: NO DOCKET #  
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387  
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv 05000388  
 AUTH. NAME: AUTHOR AFFILIATION  
 CURTIS, N.W. Pennsylvania Power & Light Co.  
 REGIP. NAME: RECIPIENT AFFILIATION

SUBJECT: Interim deficiency rept re status of Anchor Darling valve yokes. AE has advised final rept on cracked yokes on Anchor Darling valves will be available in Aug 1980. Final rept will be forwarded during Sept 1980.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: Send I&E 3 copies FSAR & all amends. 05000387  
 Send I&E 3 copies FSAR & all amends. 05000388

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
ACTION:	A/D LICENSNG 21	1		YOUNGBLOOD, B 15	1	
	RUSHBROOK, M. 20	1		SERVICE, M. 20	1	
	STARK, R. 14	1				
INTERNAL:	AD/RCI/IE	1		AEOD	1	
	D/DIR HUM FAC S	1		DIR, HUM FAC SFY	1	
	EDO & STAFF 07	1		EQUIP QUAL BR16	1	
	FIELD COOR/IE13	1		I&E 05	2	
	LIC QUAL BR	1		MPA 08	1	
	NRC PDR 02	1		OELD 23	1	
	PROC/TST REV BR	1		QA BR 10	1	
	REG FILE 01	1		RUTHERFORD, W. IE	1	
STANDRDS DEV 11	1					
EXTERNAL:	ACRS 24	16	16	LPDR 03	1	
	NSIC 04	1	1			

JUL 29 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 44 ENCL 0

NORMAN W. CURTIS  
Vice President-Engineering & Construction-Nuclear  
821-5381

July 21, 1980

Mr. Boyce H. Grier  
Director, Region I  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
UPDATE IN THE STATUS OF A DEFICIENCY ON  
ANCHOR DARLING VALVE YOKES  
ER 100450 FILE 840-4/900-10  
PLA-511

Reference: PLA-505 dated July 7, 1980

Dear Mr. Grier:

This letter serves to supplement the above referenced correspondence which advised the Commission of the subject problem under provisions of 10CFR50.55(e).

PP&L has been advised by our architect engineer, Bechtel Power Corporation, that a final report on the subject of cracked yokes on Anchor Darling valves will be available in August, 1980. Consequently, we expect to provide our final report to the Commission in September, 1980.

Very truly yours,



N. W. Curtis  
Vice President-Engineering & Construction-Nuclear

FLW:mcb

cc: Mr. Victor Stello (15)  
Director-Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555  
Mr. G. McDonald, Director  
Office of Management Information & Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. Robert M. Gallo  
U. S. Nuclear Regulatory Commission  
P. O. Box 52  
Shickshinny, Pennsylvania 18655