

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8010100337 DOC. DATE: 80/10/02 NOTARIZED: NO
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylvania
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylvania
 AUTH. NAME: CURTIS, N.W. AUTHOR AFFILIATION: Pennsylvania Power & Light Co.
 RECIP. NAME: GRIER, B.H. RECIPIENT AFFILIATION: Region 1, Philadelphia, Office of the Director

DOCKET #
 05000387
05000388

MA

SUBJECT: Supplemental deficiency report re Anchor Darling Valve Yokes.
 Condition continues to be tracked under MCAR 1-59. Final report
 will be forwarded by Jan 1981, after completion of
 manufacturer testing.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: Send I&E 3 copies FSAR & all amends. 05000387
~~Send I&E 3 copies FSAR & all amends.~~ 05000388

| ACTION: | RECIPIENT | COPIES | | RECIPIENT | COPIES | |
|--------------|-----------------|--------|------|-------------------|--------------|-----|
| | ID CODE/NAME | LTR | ENCL | | ID CODE/NAME | LTR |
| ACTION: | A/D LICENSNG | 04 | 1 | YOUNGBLOOD, B | 05 | 1 |
| | RUSHBROOK, M. | 06 | 1 | STARK, R. | 07 | 1 |
| INTERNAL: | AD/RCI/IE | 17 | 1 | AEOD | 18 | 1 |
| | ASLBP/J.HARD | | 1 | D/DIR HUM FAC15 | | 1 |
| | EDO & STAFF | 19 | 1 | EQUIP QUAL BR11 | | 1 |
| | HYD/GEO BR | 22 | 1 | I&E | 09 | 2 |
| | LIC QUAL BR | 12 | 1 | MPA | 20 | 1 |
| | NRC PDR | 02 | 1 | OELD | 21 | 1 |
| | PROC/TST REV | 13 | 1 | QA BR | 14 | 1 |
| | <u>REG FILE</u> | 01 | 1 | RUTHERFORD, N. IE | | 1 |
| STANDRDS DEV | 21 | 1 | | | | |
| EXTERNAL: | ACRS | 16 | 16 | LPDR | 03 | 1 |
| | NSIC | 08 | 1 | | | |

OCT 14 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 40 ENCL 0

R



TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101 PHONE: (215) 821-5151

NORMAN W. CURTIS
Vice President-Engineering & Construction-Nuclear
821-5381

50-387
50-388

October 2, 1980

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION
STATUS UPDATE OF DEFICIENCY ON
ANCHOR DARLING VALVE YOKES
ERS 100450/100508 FILE 840-4/900-10
PLA-551

Reference: PLA-511 dated July 21, 1980
PLA-505 dated July 7, 1980

Dear Mr. Grier:

This letter serves to supplement the above referenced correspondence which advised the Commission of the deficiency involving cracked valve yokes. The condition continues to be tracked under Bechtel's MCAR 1-59.

PP&L has been advised that the final report on the condition will be delayed pending completion of Anchor Darling's NDE testing of suspect valve yokes. Thus we expect to provide our final report under the provisions of 10CFR50.55(e) by January, 1981.

Very truly yours,

N. W. Curtis
Vice President-Engineering & Construction-Nuclear

FLW:mcb

cc: Mr. Victor Stello (15)
Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Robert M. Gallo
U. S. Nuclear Regulatory Commission
P.O. Box 52 Shickshinny, PA 18655

PENNSYLVANIA POWER & LIGHT COMPANY

B019
S1/0

8010100337

S