



TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101

PHONE: (215) 821-5151

NORMAN W. CURTIS  
Vice President-Engineering & Construction  
821-5381

MAY 27 1981

Mr. Boyce H. Grier, Director  
Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
IE BULLETIN 80-06  
ER 100450 FILE 842-3  
PLA-778

DOCKET NOS. 50-387  
AND 50-388

Dear Mr. Grier:

The following information is provided in response to IE Bulletin 80-06,  
"Engineered Safety Feature (ESF) Reset Controls".

IE Bulletin actions to be taken:

1. The drawings for all safety-related systems have been reviewed at the schematic level. The following two groups of valves do not remain in their emergency mode upon reset of an ESF actuation signal.

GROUP I

Unit 1

Unit 2

HV-E41-1F002  
 HV-E41-1F003  
 HV-E51-1F007  
 HV-E51-1F008  
 HV-E51-1F088  
 HV-E41-1F100  
 HV-E11-1F016 A&B  
 HV-E11-1F028 A&B

HV-E41-2F002  
 HV-E41-2F003  
 HV-E51-2F007  
 HV-E51-2F008  
 HV-E51-2F088  
 HV-E41-2F100  
 HV-E11-2F016 A&B  
 HV-E11-2F028 A&B

8106050 316