

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912040351 DOC. DATE: 79/11/28 NOTARIZED: NO DOCKET #
 FACILE: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylvania 0500387
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylvania 0500388
 AUTH. NAME: AUTHOR AFFILIATION
 CURTIS, N.W. Pennsylvania Power & Light Co.
 RECIPIENT NAME: RECIPIENT AFFILIATION
 GRIER, B.H. Region 1, Philadelphia, Office of the Director

SUBJECT: Forwards final deficiency report re connector pin crimping defects on control panel insert.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR. 1 ENCL. 1 SIZE: 2+40
 TITLE: Construction Deficiency Report (IOCFR50.55E)

NOTES: SEND FILE 3 CUS FSAR & ALL AMDTS.

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
	14 PM MYNER	1	1	15 BC LWR #3	1	1
	20 LA LWR #3	1	1	21 AD LWR	1	1
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	05 I&E	2	2	07 EDD & STAFF	1	1
	08 MPA	1	1	09 DEPY DIR OPM	1	1
	10 QAB	1	1	11 STANDRDS DEV	1	1
	12 JORDAN, E/IE	1	1	13 FIELD COOR/IE	1	1
	16 AD FOR ENGR	1	1	17 AD PLANT SYS	1	1
	17 AD REAC SFTY	1	1	22 DIR DPM	1	1
	23 OELD	1	1	AD/SITE TECH	1	1
	DIRECTOR DSEI	1	1	GEOSCIENCES BR	1	1
	I&C SYS BR	1	1	MATL ENG BR	1	1
	MECH ENG BR	1	1	POWER SYS BR	1	1
	S HANAUER	1	1	STRUCT ENG BR	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	24 ACRS	16	16			

DEC 5 1979

MA

TOTAL NUMBER OF COPIES REQUIRED: LTR 47 ENCL 47

Faint, illegible text scattered across the page, possibly bleed-through from the reverse side. The text is too light to transcribe accurately.

270 130



TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101 PHONE: (215) 821-5151

NORMAN W. CURTIS
Vice President-Engineering & Construction
821-5381

November 28, 1979

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION
FINAL REPORT OF CONNECTOR PIN
CRIMPING DEFECTS ON CONTROL PANEL
INSERT P853-72C
ERS 100450/100508 FILE 840-4
PLA-425

Dear Mr. Grier:

This serves to inform the Commission of a condition deemed reportable under the provisions of 10CFR 50.55(e). The condition was previously reported to the Commission under the provisions of 10 CFR Part 21 via General Electric Company letter MFN-243-79, dated September 28, 1979.

Bechtel Corporation and PP&L have evaluated the safety impact of the deficient items and have confirmed the need for reporting the condition under 10 CFR 50.55(e) as well as 10 CFR Part 21. To this end, a final report, identified as a supplement to Bechtel MCAR-1-33, is herewith submitted.

As noted in the report, the subject insert has been repaired/reworked and inspected by Bechtel QC at the SSES construction site. The repairs were conducted in accordance with approved procedures and instructions from General Electric Company and subjected to the administrative and quality verification controls of the Bechtel QA Program.

Very truly yours,

N. W. Curtis
Vice President-Engineering & Construction

Attachment
ARS:mcb

3019
11

bcc: Mr. W. E. Barberich - N4
Ms. M. C. Barto - N4
Mr. H. L. Collins - TW16.
Mr. J. W. Geiling - N5
Mr. J. D. Green - SSES
Mr. R. H. Featenby - SSES
Mr. H. F. Lilligh - Bechtel SSES
Mr. J. W. Millard - GE
Mr. J. R. Schmiedel - Bechtel SFHO
Mr. C. Turnbow - Bechtel SSES
Mr. E. M. Mead - N5
Mr. M. R. Muir - Bechtel SFHO
Mr. E. M. Nagel - TW2
Mr. A. R. Sabol - N4
Mr. P. F. Schock - TW4
Mr. M. J. Silberg - (Shaw, Pittman, Potts & Trowbridge)
Mr. R. J. Shovlin - N4
SP&E Correspondence File - N3
Susquehanna Letter File - N3

Mr. Boyce H. Grier

- 2 -

November 28, 1979

cc: Mr. Robert M. Gallo
U. S. Nuclear Regulatory Commission
P. O. Box 52
Shickshinny, Pennsylvania 18655

~~Mr. G. McDonald~~
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Victor Stello (15)
Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555