

THE CHURCH OF
JESUS CHRIST
OF LATTER-DAY SAINTS

RUPERT ID FM GROUP
1814 H Street
Rupert, Idaho 83350-1054
Phone: 1-208-434-1421
Toll free: 1-866-434-1421
Facsimile: 1-208-434-1423


January 9, 2018

Director of FSME
Attn: GLTS
USNRC
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on January 9, 2018 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2022. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Rhonda Shaw @ 208-434-1421.

Sincerely,



Rhonda Shaw
Rupert ID AA

Encl.

SERIAL NUMBER SPREADSHEET

Company Name	Rupert ID FM Group	Date	10-30-17
Address 1	1814 H Street	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	249009253 ^{FMACB} 235157
City/State	Rupert, ID	Contact Name	Rhonda Shaw
Zip/Post Code	83350	Contact Phone	208-434-1421
Country	United States	Contact FAX	N/A
		Contact E-mail	ShawR@ldschurch.org

*Rupert
3rd*

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	SRB Tech.	B100	555420	03	1993	20 "Ci"
2	SRB Tech.	B100	555424	03	1993	20 "Ci"
3	SRB Tech.	B100	555423	03	1993	20 "Ci"
4	SRB Tech.	B100	555415	03	1993	20 "Ci"
5	SRB Tech.	B100	538464	03	1995	20 "Ci"
6	SRB Tech.	B100	588459	03	1995	20 "Ci"
7	SRB Tech.	B100	588462	03	1995	20 "Ci"
8	SRB Tech.	B100	588458	03	1995	20 "Ci"
9	SRB Tech.	B100	588456	03	1995	20 "Ci"
10	SRB Tech.	B100	588457	03	1995	20 "Ci"
11	SRB Tech.	B100	620281	08	1997	20 "Ci"
12	SRB Tech.	B100	620282	08	1997	20 "Ci"
13	SRB Tech.	B100	588452	03	1995	20 "Ci"
14	SRB Tech.	B100	588446	03	1995	20 "Ci"
15	SRB Tech.	B100	588448	03	1995	20 "Ci"

(14)

320

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	Rupert ID FM Group	Date	10-30-17
Address 1	1814 H Street	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	2430092671
City/State	Rupert, ID	Contact Name	Rhonda Shaw
Zip/Post Code	83350	Contact Phone	208-434-1421
Country	United States	Contact FAX	N/A
		Contact E-mail	ShawR@ldschurch.org

(16)

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "C" or "TBq"
				Month	Year	
1	SRB Tech.	B100	555421	03	1993	20 "C"
2	SRB Tech.	B100	588463	03	1995	20 "C"
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	Rupert ID FM Group	Date	10-30-17
Address 1	1814 H Street	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	FMACO- 25236 235164
City/State	Rupert, ID	Contact Name	Rhonda Shaw
Zip/Post Code	83350	Contact Phone	208-434-1421
Country	United States	Contact FAX	N/A
		Contact E-mail	ShawR@ldschurch.org

R57

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	SRB Tech.	B100	631232			20 "CI"
2	SRB Tech.	B100	631233			20 "CI"
3	SRB Tech.	B100	631239			20 "CI"
4	SRB Tech.	B100	631238			20 "CI"
5	SRB Tech.	B100	631242			20 "CI"
6	Omniglo	700-C-20	420	08	1993	20 "CI"
7	Omniglo	700-C-20	426	08	1993	20 "CI"
8	SRB Tech.	B100	631237			20 "CI"
9	Omniglo	700-C-20	425	08	1993	20 "CI"
10	SRB Tech.	B100	631234			20 "CI"
11	SRB Tech.	B100	631235			20 "CI"
12	Omniglo	700-C-20	418	08	1993	20 "CI"
13	Omniglo	700-C-20	423	08	1993	20 "CI"
14	SRB Tech.	B100	631236			20 "CI"
15	Omniglo	700-C-20	419	08	1993	20 "CI"

300

The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs---not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

31

SERIAL NUMBER SPREADSHEET

Company Name	Rupert ID FM Group	Date	10-30-17
Address 1	1814 H Street	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	FMACQ- 2208 235165
City/State	Rupert, ID	Contact Name	Rhonda Shaw
Zip/Post Code	83350	Contact Phone	208-434-1421
Country	United States	Contact FAX	N/A
		Contact E-mail	ShawR@idschurch.org

Acquia

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	Safety Light	SLX-60	412816	06	2007	11.5 "Ci"
2	SRB Tech.	B100	588450	03	1995	20 "Ci"
3	SRB Tech.	B100	578669	08	1994	20 "Ci"
4	SRB Tech.	B100	631243	07	1998	20 "Ci"
5	Safety Light	SLX-60	412815	06	2007	11.5 "Ci"
6	SRB Tech.	B100	588453	03	1995	20 "Ci"
7	SRB Tech.	B100	588447	03	1995	20 "Ci"
8	SRB Tech.	B100	629124			20 "Ci"
9	SRB Tech.	B100	642924	04	1999	20 "Ci"
10	SRB Tech.	B100	642923	04	1999	20 "Ci"
11	SRB Tech.	B100	631245	07	1998	20 "Ci"
12	SRB Tech.	B100	588449	03	1995	20 "Ci"
13	SRB Tech.	B100	631241	07	1998	20 "Ci"
14	SRB Tech.	B100	631244	07	1998	20 "Ci"
15	SRB Tech.	B100	631240	07	1998	20 "Ci"

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

343

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

46

SERIAL NUMBER SPREADSHEET

Company Name	Rupert ID FM Group	Date	10-30-17
Address 1	1814 H Street	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	FMACQ-213878
City/State	Rupert, ID	Contact Name	Rhonda Shaw
Zip/Post Code	83350	Contact Phone	208-434-1421
Country	United States	Contact FAX	N/A
		Contact E-mail	ShawR@ldschurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	SRB Tech.	B100	629126			20 "Ci"
2	SRB Tech.	B100	588451	03	1995	20 "Ci"
3	SRB Tech.	B100	631246	07	1998	20 "Ci"
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

49