

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8901110403 DOC. DATE: 89/01/06 NOTARIZED: NO DOCKET #
 FACIL: 50-260 Browns Ferry Nuclear Power Station, Unit 2, Tennessee 05000260
 AUTH. NAME AUTHOR AFFILIATION
 GRIDLEY, R. Tennessee Valley Authority *See Rpt.*
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Electrical Cable Separations Rept."

DISTRIBUTION CODE: D030D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+54
 TITLE: TVA Facilities - Routine Correspondence

NOTES: 1 Copy each to: S. Black, J.G. Partlow, S. Richardson 05000260
 B.D. Liaw, F. McCoy.

	RECIPIENT		COPIES				
	ID CODE/NAME	LTR	ENCL				
	SIMMS, M	1	1	PD	1	1	
	GEARS, G	1	1				
INTERNAL:	ACRS	1	1	ADM/LFMB	1	0	
	NUDOCS-ABSTRACT	1	1	OGC/HDS2	1	0	
	<u>REG FILE 01</u>	1	1				
EXTERNAL:	LPDR	1	1	NRC PDR	1	1	
	NSIC	1	1				
NOTES:		5	5				

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 16 ENCL 14

m/A-2
ect

R
I
D
S
/
A
D
D
S

42

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
5N 157B Lookout Place

JAN 06 1989

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Gentlemen:

In the Matter of)
Tennessee Valley Authority)

Docket No. 50-260

BROWNS FERRY NUCLEAR PLANT (BFN) - ELECTRICAL CABLE SEPARATION


This letter transmits BFN's Electrical Cable Separation Report (enclosure 1) as committed in my letter dated November 10, 1988. This report provides the details of our evaluations and a summary of results and corrective actions. As a result of these evaluations and with concurrent implementation of the resulting corrective actions, TVA has the confidence level necessary to ensure that the routing of cables at BFN will meet the existing separation criteria.

In the meeting with NRC on November 30, 1988, TVA reported that 242 modifications had been identified that are required before restart. The enclosed report identifies 226 modifications that are required. The difference is due to the elimination of duplicate deficiencies identified by the Ebasco and TVA discovery efforts.

A summary list of commitments is provided in enclosure 2. Please refer any questions concerning this submittal to Patrick Carrier, BFN Site Licensing, (205) 729-3570

Very truly yours,

TENNESSEE VALLEY AUTHORITY


R. Gridley, Manager
Nuclear Licensing and
Regulatory Affairs

Enclosures
cc: See page 2

8901110403 890106
PDR ADOCK 05000260
P PDC

D030
11

12

12

12

12

12

12

12

12

U.S. Nuclear Regulatory Commission

JAN 06 1989

cc (Enclosures):

Ms. S. C. Black, Assistant Director
for Projects
TVA Projects Division
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852

Mr. F. R. McCoy, Assistant Director
for Inspection Programs
TVA Projects Division
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Browns Ferry Resident Inspector
Browns Ferry Nuclear Plant
Route 12, Box 637
Athens, Alabama 35609-2000

32

Page 10

10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100