

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIOS)

ACCESSION NBR: 8106050324 DOC. DATE: 81/06/01 NOTARIZED: NO DOCKET #  
 FACIL: 50-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220  
 50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha 05000410

AUTH. NAME: AUTHOR AFFILIATION  
 DISE, D.P. Niagara Mohawk Power Corp.  
 RECIP. NAME: RECIPIENT AFFILIATION  
 EISENHUT, D. Division of Licensing

SUBJECT: Notifies that mods to scram discharge sys will be completed by end of current refueling outage. Mods establish compliance w/criteria developed by BWR owners group.

DISTRIBUTION CODE: B021S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Correspondence for Operating & Non-Operating Facility (e.g. North Ann

NOTES:


ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	IPPOLITO, T. 04	1		LIC BR #2 BC 04	1	
	NORRIS, S.	1		LIC BR #2 LA	1	
	POLK, P. 05	1		LYNCH, D. 05	1	
INTERNAL:	A/D CORE & CS	1	0	ACCID EVAL BR28	1	
	AUX SYS BR 08	1		CHEM ENG BR 09	1	
	COVT SYS BR 10	1		CORE PERF BR 11	1	
	DIR, HUM FAC S12	1		DIR, LICENSING	1	
	EFF TR SYS BR13	1		EMRG PRP DEV	1	
	EMRG PRP LIC	3		EQUIP QUAL BR14	1	
	FEYA-REP DIV	1		GEOSCIEN BR 15	4	
	HUM FACT ENG 16	1		HUM FACT ENG BR	1	
	HYD/GEO BR 17	1		I&C SYS BR 18	1	
	I&E 07	3		LIC GUID BR	1	
	LIC QUAL BR	1		MATL ENG BR 19	1	
	MECH ENG BR 20	1		MPA	1	
	NRC PDR 02	1		OELD	1	
	OP LIC BR	1		OR ASSESS BR	1	
	POWER SYS BR 21	1		PROC/TST REV 22	1	
	QA BR 23	1		RAD ASSESS BR24	1	
	REAC SYS BR 25	1		REG FILE 01	1	
	SIT ANAL BR 26	1		STRUCT ENG BR27	1	
EXTERNAL:	ACRS 29	16	1	LPDR 03	1	
	NSIC 06	1				

JUN 08 1981

TOTAL NUMBER OF COPIES REQUIRED: LTR 67 ENCL 0

1950 年 11 月 11 日

June 1, 1981



Director of Licensing  
Attention: Mr. Darrell Eisenhut, Director  
United States Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Eisenhut:

As outlined in our October 27, 1980 letter, modifications to the scram discharge system will be completed by the end of the current refueling outage. These will establish compliance with the criteria developed by the BWR Owners subgroup. Exceptions to this are presented in our January 30, 1981 letter. The staff's Generic Safety Evaluation Report on BWR Scram Discharge System indicated that these criteria provided an acceptable basis for resolution of problems associated with the scram discharge system.

It is Niagara Mohawk's understanding that compliance with these criteria eliminates the need for interim actions. Therefore, the equipment for continuous monitoring of the scram discharge system headers (i.e., UT equipment) will not be reinstalled.

Sincerely,

NIAGARA MOHAWK POWER CORPORATION

A handwritten signature in cursive script, appearing to read "D. P. Dise".

D. P. Dise  
Vice President Engineering

BDW:ja

Boa  
~~Boa~~  
S  
i/o

8106050324

P

