REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

CATEGORY

ACCESSION NBR: 9607290220 DOC.DATE: 96/07/22 NOTARIZED: NO DOCKET # 05000260 FACIL: 50-260 Browns Ferry Nuclear Power Station, Unit 2, Tennessee AUTHOR AFFILIATION AUTH.NAME SALAS, P. Tennessee Valley Authority RECIPIENT AFFILIATION RECIP.NAME Document Control Branch (Document Control Desk) PRONTS SUBJECT: Forwards "BFN Unit 2 Cycle 8 ISI NIS-1 Rept." C DISTRIBUTION CODE: A047D COPIES RECEIVED:LTR SIZE: ENCL TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code - GL-89 Α 04 Т NOTES:

	RECIPIENT ID CODE/NAME PD2-3 WILLIAMS,J.	COPII LTTR 1 1	ES ENCL 1 1	RECIPIENT ID CODE/NAME PD2-3-PD	COP: LTTR 1	
INTERNAL:	ACRS	6	0	AEOD/SPD/RAB	1	ļ
C	FILE CENTER OF	1	1	NRR/DE/ECGB	1	1
	NRR/DE/EMCB	l	1	NRR/DE/EMEB	1	1
	NUDOCS-ABSTRACT	1	1	OGC/HDS3	1	0
	RES/DET/EMMEB	1	1	RES/DSIR/EIB	l	1
EXTERNAL:	LITCO ANDERSON	1	1	NOAC	1	1
	NRC PDR	1	1	,		

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM OWFN 5D-5(EXT. 415-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 21 ENCL 14

MAE

E

G

0

R

Y

1

D

0

C

U


Μ

Ε

N

T

1





Tennessee Valley Authority, Post Office Box 2000, Decatur, Alabama 35609

JUL 22 1996

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Gentlemen:

In the Matter of Tennessee Valley Authority Docket No. 50-260

BROWNS FERRY NUCLEAR PLANT (BFN) - UNIT 2 CYCLE 8 - INSERVICE INSPECTION, AND REPAIR AND REPLACEMENTS - SUMMARY REPORTS

)


In accordance with paragraphs IWA-6220 and IWA-6230 of the American Society of Mechanical Engineers Boiler and Pressure Vessel Code, Section XI, 1986 Edition, TVA is submitting the BFN Unit 2 summary reports for NRC review. The summary reports are for inservice inspection, and repair and replacement activities for Unit 2 Cycle 8 from November 24, 1994, through April 24, 1996. Additionally, TVA is including an update to the Unit 2 Cycle 6 inservice inspection report and corrections to the Unit 2 Cycle 6 repair and replacement report. These reports were initially transmitted to NRC by TVA letter dated August 27, 1993.

Enclosure 1 contains BFN's Unit 2 inservice inspection summary reports for Code Class 1 and 2 pressure retaining components and their supports. Enclosure 2 contains repair and replacement reports for Code Class 1 and 2 components and supports. Additionally, Enclosure 3 provides an update to BFN's Unit 2 Cycle 6 inservice inspection report. Enclosure 4 provides a correction to NIS-2 Forms for two workplans submitted in the Unit 2 Cycle 6 repair and replacement data report.

290071

9607290220 960722 PDR ADDCK 05000260 PDR

A0471/1



U.S. Nuclear Regulatory Commission Page 2 JUL 2 2 1996

There are no commitments contained in this letter. If you have any questions regarding these reports, please contact me at (205) 729-2636.

Sincerely

Pedro Salas Manager of Site Licensing

Enclosures cc: See page 2

• 7 ъ # •


U.S. Nuclear Regulatory Commission Page 3

JUL 22 1996

Enclosures cc (Enclosures): Mr. Mark S. Lesser, Branch Chief U.S. Nuclear Regulatory Commission Region II 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

> NRC Resident Inspector Browns Ferry Nuclear Plant 10833 Shaw Road Athens, Alabama 35611

Mr. J. F. Williams, Project Manager U.S. Nuclear Regulatory Commission One White Flint, North 11555 Rockville Pike Rockville, Maryland 20852





TENNESSEE VALLEY AUTHORITY BROWNS FERRY NUCLEAR PLANT (BFN) UNIT 2

INSERVICE INSPECTION, AND AUGMENTED EXAMINATIONS SUMMARY REPORT FOR CYCLE 8 OPERATION

(SEE ATTACHED)

