

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9806300526 DOC.DATE: 98/06/24 NOTARIZED: NO DOCKET #  
 FACIL:50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha 05000410  
 AUTH.NAME AUTHOR AFFILIATION  
 DAHLBERG,K.A. Niagara Mohawk Power Corp.  
 RECIP.NAME RECIPIENT AFFILIATION  
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-014-00, "Systems Outside Design Basis Due to Incorrect Valve Weights." Rept also satisfies evaluation, notification & reporting obligations of 10CFR21.

DISTRIBUTION CODE: IE28T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+6  
 TITLE: Licensee Event Report (LER) & Part 21 Rept Combination (50 Dkt)

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-1 LA HOOD,D	1 1 1 1	PD1-1 PD	1 1
INTERNAL:	ACNW	1 1	ACRS	1 1
	AEOD/SPD/RAB	2 2	AEOD/SPD/RRAB	1 1
	DEDRO	1 1	<del>FILE CENTER</del>	1 1
	NRR/DE/EELB	1 1	NRR/DE/EMCB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HICB	1 1
	NRR/DRCH/HOHB	1 1	NRR/DRCH/HQMB	1 1
	NRR/DRPE	1 1	NRR/DRPM/PECB	1 1
	NRR/DRPM/PECB/B	1 1	NRR/DREW	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SPSB/B	1 1
	NRR/DSSA/SRXB	1 1	RES/DET/EIB	1 1
	RGN 1	1 1	RGN 2	1 1
	RGN 3	1 1	RGN 4	1 1
	RGN1 FILE 01	1 1		
EXTERNAL:	INPO RECORD CTR	1 1	L ST LOBBY WARD	1 1
	LITCO STUART,VA	1 1	NOAC MAYS,G	1 1
	NOAC QUEENER,D.	1 1	NRC PDR	1 1
	NUDOCS FULL TXT	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:  
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 36 ENCL 36

A04

C  
A  
T  
E  
G  
O  
R  
Y  
1  
D  
O  
C  
U  
M  
E  
N  
T





NIAGARA MOHAWK

GENERATION  
BUSINESS GROUP

NINE MILE POINT NUCLEAR STATION/LAKE ROAD, P.O. BOX 63, LYCOMING, NEW YORK 13093

June 24, 1998  
NMP2L 1794

United States Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

RE: Docket No. 50-410  
LER 98-14

Gentlemen:

In accordance with 10CFR50.73(a)(2)(i)(B) and 10CFR50.73 (a)(2)(ii)(B), we are submitting LER 98-14, "Systems Outside the Design Basis Due to Incorrect Valve Weights." This event was caused by a vendor-related deficiency associated with Velan Engineering Companies. In accordance with 10CFR21.2(c), this LER satisfies the evaluation, notification, and reporting obligations of 10CFR Part 21.

Very truly yours,

Kim A. Dahlberg  
Plant Manager - Unit 2

KAD/TWP/sc  
Attachment

xc: Mr. H. J. Miller, Regional Administrator, Region I  
Mr. B. S. Norris, Senior Resident Inspector  
Records Management

9806300526 980624  
PDR ADOCK 05000410  
S PDR

1/1  
7228

