

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8808010216 DOC.DATE: 88/07/21 NOTARIZED: NO DOCKET #
 FACIL:50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylva 05000387
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylva 05000388
 AUTH.NAME AUTHOR AFFILIATION
 KEISER,H.W. Pennsylvania Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 RUSSELL,W.T. Region 1, Ofc of the Director

See Rpt.

SUBJECT: Forwards util rept on control drive housing cap screw corrosion. R

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+105 I
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response D

NOTES:LPDR 2 cys Transcripts. 05000387S
 LPDR 2 cys Transcripts. 05000388

| | RECIPIENT ID CODE/NAME | COPIES LTR ENCL | RECIPIENT ID CODE/NAME | COPIES LTR ENCL | |
|-----------|---------------------------|--------------------|---------------------------|--------------------|---|
| | Pd1-2 PD | 1 1 | THADANI,M | 2 2 | A |
| INTERNAL: | ACRS | 2 2 | AEOD | 1 1 | D |
| | DEDRO | 1 1 | NRR MORISSEAU,D | 1 1 | D |
| | NRR/DLPQ/PEB 11 | 1 1 | NRR/DLPQ/QAB 10 | 1 1 | S |
| | NRR/DOEA DIR 11 | 1 1 | NRR/DREP/EPB 10 | 1 1 | |
| | NRR/DREP/RPB 10 | 2 2 | NRR/DRIS DIR 9A | 1 1 | |
| | NRR/PMAS/ILRB12 | 1 1 | NUDOCS-ABSTRACT | 1 1 | |
| | OE LIEBERMAN,J | 1 1 | OGC 15-B-18 | 1 1 | |
| | <u>REG FILE</u> 02 | 1 1 | RES/DSIR DEPY | 1 1 | |
| | RGNI FILE 01 | 1 1 | | | |

EXTERNAL: LPDR 2 2 NRC PDR 1 1
 NSIC 1 1

NOTES: 2 2 R

R
I
D
S
/
A
D
D
S



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101-1179 • 215/770-5151

JUL 21 1988

Harold W. Keiser
Senior Vice President-Nuclear
215/770-4194

Mr. William T. Russell
Regional Administrator Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
CRD BOLT REPORT
PLA-3062 FILE R41-2

Docket Nos. 50-387
and 50-388

Dear Mr. Russell:

As requested by your staff, attached is a copy of General Electric's Report on the Control Rod Drive Housing Cap Screw Corrosion. This letter completes our action on this item.

Very truly yours,


H. W. Keiser

Attachment

cc: NRC Document Control Desk (original)
NRC Region I
Mr. M. C. Thadani, NRC Project Manager
Mr. F. I. Young, NRC Sr. Resident Inspector

8808010216 880721
PDR ADDCK 05000387
P PNU

IFD
11