## PALISADES PLANT

NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

## LICENSEE EVENT REPORT

	CONTROL BLOCK: [ ] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	MIPALI 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 5 5 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 67 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 2 5 5 7 1 1 1 0 7 9 8 0 4 2 1 8 0 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	During routine surveillance of containment purge valves, it was found that
0 3	the redundant T-ring air supplies for the 12-inch and 48-inch purge valves
04	had leakage in excess of acceptance criteria. Normal air supply was
0 5	Loperable. Condition classified reportable under TS 6.9.2.B.4 on 3-21-80.
0 6	L
0 7	
08	9 80
0 9	SYSTEM CAUSE COMPONENT CODE SUBCODE SU
	SEQUENTIAL OCCURRENCE REPORT TYPE NO.  17 REPORT VEAR REPORT OCCURRENCE REPORT NO.  18 O O O O O O O O O O O O O O O O O O O
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER  F B B 19 Z 20 Z 21 O O O O N Z 23 Y 24 A 25 F 1 2 5 26  CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10	Leaks were primarily through fittings and valve packings. Replacement
111	of CV-1806 and CV-1807 with blank flanges has been completed. Repairs
1 2	to T-ring air supplies to CV-1812 and 1814 will be completed prior to
1 3	start-up.
7 8	
1 5 F	ACILITY * POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  LG 28 LO 10 29 NA RETHOD OF DISCOVERY DESCRIPTION 32  9 10 12 13 44 45 45 45 45 80
1 6 RE	CTIVITY CONTENT LEASED OF RELEASE AMOUNT OF ACTIVITY (35)  LOCATION OF RELEASE (36)  NA N
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  O   O   O   (37)   Z   (38)   NA
1 2	PERSONNEL INJURIES NUMBER DESCRIPTION 41  NA
•	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION
1 9	VA NA
2 0	POBLICITY SSUED DESCRIPTION (45)  NA NAC USE ONLY NA
, 8	9 10 68 60 80