



~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
245 PEACHTREE CENTER AVENUE NE, SUITE 1200
ATLANTA, GEORGIA 30303-1257

February 20, 2018

Mr. Joseph W. Shea
Vice President, Nuclear Regulatory Affairs
and Support Services Licensing
Tennessee Valley Authority
1101 Market Street, LP 4A
Chattanooga, TN 37402-2801

SUBJECT: BROWNS FERRY NUCLEAR PLANT, UNITS 1, 2, AND 3 – U.S. NUCLEAR
REGULATORY COMMISSION INSPECTION PROCEDURE 95001
SUPPLEMENTAL INSPECTION REPORT 05000259/2018440,
05000260/2018440 AND 05000296/2018440 AND CLOSED REGULATORY
PERFORMANCE MEETING

Dear Mr. Shea:

On February 02, 2018, the U.S. Nuclear Regulatory Commission (NRC) completed a supplemental inspection pursuant to Inspection Procedure 95001, "Supplemental Inspection for One or Two White Inputs in a Strategic Performance Area," at your Browns Ferry Nuclear Plant, Units 1, 2, and 3, and discussed the results of this inspection with Mr. S. Bono and other members of your staff. The results of this inspection are documented in the enclosed report.

In accordance with the NRC Reactor Oversight Process Action Matrix, this supplemental inspection was performed to follow-up on a greater than green finding with low to moderate safety significance which was issued in the second quarter of 2017. This issue was previously documented and assessed in NRC Inspection Report 05000259, 260, 296/2017406. The NRC was informed on November 17, 2017 of your staff's readiness for this inspection.

The objectives of this supplemental inspection were to provide assurance that: (1) the root causes and the contributing causes for the risk-significant issues were understood; (2) the extent of condition and extent of cause of the issues were identified; and (3) corrective actions were or will be sufficient to address and preclude repetition of the root and contributing causes.

Based on the results of this inspection, the NRC has concluded that you have adequately completed a root cause analysis of the issue, and have identified appropriate corrective actions to prevent recurrence of the issue. No findings were identified concerning the root cause evaluation and corrective actions.

~~Enclosure(s) transmitted herewith contain(s) SUNSI. When separated from enclosure(s), this transmittal document is decontrolled.~~

~~LIMITED INTERNAL
DISTRIBUTION PERMITTED~~

~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

J. Shea

2

The NRC has determined that inspection objectives stated above have been met. As a result, the violation is considered closed. Therefore in accordance with IMC 0305, "Operating Reactor Assessment Program," the performance issue shall not be considered in the Action Matrix after the end of the first quarter 2018.

This letter will be made available for public inspection and copying at <https://www.nrc.gov/reading-rm/adams.html> and at the NRC Public Document Room in accordance with 10 CFR 2.390, "Public Inspections, Exemptions, Requests for Withholding."

However, the enclosed report contains Security-Related Information, so the enclosed report will not be made publicly available in accordance with 10 CFR 2.390(d)(1). If you choose to provide a response that contains Security-Related Information, please mark your entire response "Security-Related Information–Withhold from public disclosure under 10 CFR 2.390" in accordance with 10 CFR 2.390(d)(1) and follow the instructions for withholding in 10 CFR 2.390(b)(1). The NRC is waiving the affidavit requirements for your response in accordance with 10 CFR 2.390(b)(1)(ii).

Sincerely,

/RA/

Binoy Desai, Chief
Plant Support Branch
Division of Reactor Safety

Docket Nos: 50-259, 50-260 and 50-296
License Nos: DPR-33, DPR-52 and DPR-68

Enclosure:

~~NRC IR 05000259/2018440, 260/2018440~~

~~and 296/2018440~~

~~w/Attachment: Supplemental Information (OUO)~~

cc: (See page 3)

J. Shea

3

cc:

Mr. F. E. Marcussen
Director, Nuclear Security
Tennessee Valley Authority
1101 Market Street, LP 1A
Chattanooga, TN 37402-2801

Mr. R. Dawson, Jr.
Senior Manager, Site Security
Browns Ferry Nuclear Plant
Tennessee Valley Authority
P.O. Box 2000
PAB 2G-BFN
Athens, AL 35609

Mr. D. Lang Hughes
General Manager,
Site Operations
Browns Ferry Nuclear Plant
Tennessee Valley Authority
P.O. Box 2000
NAB 1A-BFN
Decatur, AL 35609

Mr. Glen E. Pry
Plant Manager
Browns Ferry Nuclear Plant
Tennessee Valley Authority
P.O. Box 2000
POB 2C-BFN
Decatur, AL 35609

Mr. James A. Kent
Director, Plant Support
Browns Ferry Nuclear Plant
Tennessee Valley Authority
P.O. Box 2000
NAB 1A-BFN
Decatur, AL 35609

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

J. Shea

SUBJECT: BROWNS FERRY NUCLEAR PLANT, UNITS 1, 2, AND 3 – U.S. NUCLEAR REGULATORY COMMISSION INSPECTION PROCEDURE 95001 SUPPLEMENTAL INSPECTION REPORT 05000259/2018440, 05000260/2018440 AND 05000296/2018440 AND CLOSED REGULATORY PERFORMANCE MEETING dated February 20, 2018

DISTRIBUTION:

- N. Simonian, NSIR
- D. Huyck, NSIR
- C. Johnson, NSIR
- J. Rubenstone, NMSS
- A. Masters, RII, DRP
- S. Ninh, RII, SPE
- J. Seat, RII, PE
- D. Dumbacher, SRI
- A. Ruh, RII, RI
- M. Kirk, RII, RI
- S. Price, RII, ORA/RC
- K. Sloan, RII, EICS
- RIDSNRRDIRS
- PUBLIC

* See previous page for concurrence

PUBLICLY AVAILABLE
 NON-PUBLICLY AVAILABLE
 SENSITIVE
 NON-SENSITIVE
 ADAMS: Yes
 ACCESSION NUMBER: _____
 SUNSI REVIEW COMPLETE
 FORM 665 ATTACHED

OFFICE	RII:DRS/PSB	RII:DRS/PSB	RII:DRS/PSB	RII:DRP/BR6	RII:DRS/PSB
SIGNATURE	JPT	JDG4	BBD	ADM2	BBD
NAME	J. Tornow	D. Golden	B. Desai	A. Masters	B. Desai
DATE	2/ 20 /2018	2/ 14 /2018	2/14 /2018	2/ 20 /2018	2/ 20 /2018
E-MAIL COPY	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY