



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION III
2443 WARRENVILLE RD. SUITE 210
LISLE, IL 60532-4352

MAR 09 2018

William D. Reeve
Radiation Safety Officer
JAN X-Ray Services, Inc.
dba JANX
P.O. Box 190
8550 E. Michigan Avenue
Parma, MI 49269

Dear Mr. Reeve:

Enclosed is Amendment No. 32 to your NRC Material License No. 21-16560-01 in accordance with your request. Please note that your license format has been changed based on our new licensing process.

In addition, based on the information you provided and the Sealed Sources and Devices Registry (SSDR) data we updated the authorized material and devices listed in Items 6, 7, 8, and 9 in the license. In accordance with the licensing policy, we also updated License Condition No. 10 regarding the location of use and License Condition Nos. 14 and 15 regarding the sealed source leak test requirements. We deleted License Condition No. 18 regarding the transportation requirement in the previous amendment because the requirement is already specified in the regulations. Based on the licensed material and activities authorized under Items 6.Q. through 6.T., a program code 03124 associated with fee category 3.P. as specified in 10 CFR 171.16(d) was added to your license. A description of the program code can be found in Appendix G to NUREG-1556, Volume 20 which is published on the NRC web site at <https://www.nrc.gov/docs/ML0102/ML010250252.pdf>.

In our requests for additional formation dated January 12, 2018 and February 9, 2018, we request for information regarding the ThermoRetec Model 64-764 calibrator listed in the previous license amendment. However, your responses dated January 24, 2018 and February 24, 2018 did not address this device. Based on our policy, we will list this device in your license until we received adequate information about it.

You request to delete the following field locations from your license: 5091 E. Woodsmall Dr., Terre Haute, Indiana, 4726 W. Baker Rd., Coleman, Michigan, 12500 76th Ave., Allendale, Michigan, 11499 Easton Rd., Rives Junction, Michigan, 2934 Ridgecrest Dr., Casper, Wyoming, 9475 N. Cut Rd., Roscommon, Michigan, 2701 Clark Dr., Jackson, Michigan, and 4622 Wilson Burg Rd., Salem, West Virginia. Based on the information provided, we have concluded that all licensable radioactive material has been removed from the facilities located at those locations and residual radioactive material attributable to licensed activities does not exceed NRC requirements. Therefore, we have authorized to release the facilities located at those addresses for unrestricted use.

The enclosed document contains sensitive security-related information.
When separated from this cover letter this letter is uncontrolled.

W. Reeve

-2-

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the U.S. Nuclear Regulatory Commission, Region III office at (630) 829-9887 so that we can provide appropriate corrections and answers.

You will be periodically inspected by NRC. Failure to conduct your program in accordance with NRC regulations, license conditions, and representations made in your license application and supplemental correspondence with NRC will result in enforcement action against you. This could include issuance of a notice of violation, or imposition of a civil penalty, or an order suspending, modifying or revoking your license as specified in the General Statement of Policy and Procedure for NRC Enforcement Actions. Since serious consequences to employees and the public can result from failure to comply with NRC requirements, prompt and vigorous enforcement action will be taken when dealing with licensees who do not achieve the necessary meticulous attention to detail and the high standard of compliance which NRC expects of its licensees.

The NRC's Safety Culture Policy Statement became effective in June 2011. While a policy statement and not a regulation, it sets forth the agency's *expectations* for individuals and organizations to establish and maintain a positive safety culture. You can access the policy statement and supporting material that may benefit your organization on NRC's safety culture Web site at <http://www.nrc.gov/about-nrc/regulatory/enforcement/safety-culture.html>. We strongly encourage you to review this material and adapt it to your particular needs in order to develop and maintain a positive safety culture as you engage in NRC-regulated activities.


NRC's Regulatory Issue Summary (RIS) 2005-31 provides criteria to identify security-related sensitive information and guidance for handling and marking of such documents. This ensures that potentially sensitive information is not made publicly available through ADAMS, the NRC's electronic document system. Pursuant to NRC's RIS 2005-31 and in accordance with 10 Code of Federal Regulations 2.390, the enclosed license document is exempt from public disclosure because its disclosure to unauthorized individuals could present a security vulnerability. The RIS may be located on the NRC Web site at: <http://www.nrc.gov/reading-rm/doc-collections/gen-comm/reg-issues/2005/ri200531.pdf> and the link for frequently asked questions regarding protection of security related sensitive information may be located at: <http://www.nrc.gov/reading-rm/sensitive-info/faq.html>.

W. Reeve

-3-

A copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Sincerely,



Frank P. D. Tran
Materials Licensing Branch

License No. 21-16560-01
Docket No. 030-11772

Enclosure: Amendment No. 32