NE FORM 366 UPDATE REPORT - DEVIOUS REPORT DATE 4/19/79 SNUCLEAR REGULATURY COMMISSION
CONTROL BLOCK:
$ \begin{array}{ c c c c c c } \hline 0 & 1 \\ \hline 7 & 8 \\ \hline 9 \\ \hline \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\$
$ \begin{array}{c} \text{CON'T} \\ \hline 0 1 \\ 7 \\ 8 \end{array} \\ \begin{array}{c} \text{REPORT} \\ \text{SOURCE} \\ \hline 50 \\ \hline 61 \\ \hline 0 \\ 61 \\ \hline 0 \\ 61 \\ \hline 0 \\ \hline 0 \\ 61 \\ \hline 0 \\ \hline$
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)           0         2         During cold shutdown operations, with No. 1 fire pump out of service for planned
0 3   maintenance, No. 2 fire pump did not automatically start when header pressure
0 4 dropped to 75 psig. An overhead annunciator in control room alarmed at 65 psig and
0 5 an operator was sent to the fire pump house to investigate. The operator initiated
0 6 a manual start and returned system pressure to normal. T/S 3.7.10.1 Action b was
0 7   initiated at 1130 hours and was terminated at 1855 hours when the auto start logic
0       8       9         7       8       9         80
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
ID     LER'RO     EVENT YEAR     REPORT NO.     CODE     TYPE     NC.       ID     REPORT     7     9     0     0     0     1     X     1
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
10 A weak cell in both A and B batteries has been the only identified cause of this
1 1 Occurrence. The entire starting and charging circuitry and components were tested
[1 2] and found to be operating satisfactory. New batteries were installed and have
13 provided satisfactory operation.
FACILITY STATUS       % POWER       OTHER STATUS       30       METHOD OF DISCOVERY       DISCOVERY DESCRIPTION       32         1       5       G       28       0       0       0       29       N/A       A       A       A       A       A       A       A       A       A       A       B0         7       8       9       10       12       13       44       45       45       45       45       80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY $35$ 1 6 2 33 2 33 2 33 2 34 10 11 44 45 LOCATION OF RELEASE $36N/A30$
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 0 0 0 (37) Z (38) N/A
PERSONNEL INJURIES
$\begin{bmatrix} 1 & 3 \\ 7 & 2 \end{bmatrix} \begin{bmatrix} 0 & 0 & 0 \\ 11 & 12 \end{bmatrix} \begin{bmatrix} 0 & 0 \\ 11 & 12 \end{bmatrix} \begin{bmatrix} 0 & 0 \\ 12 \end{bmatrix} \begin{bmatrix} 0 & 0 \\ 13 \end{bmatrix} \begin{bmatrix} 0 & 0 \\ 14 \end{bmatrix} \begin{bmatrix} $
30         30         30           PUBLICITY         ISSUED         DESCRIPTION         45         7906050304         NRC USE ONLY           ISSUED         Z         44         N/A         IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
7 8 9 10 68 69 20 NAME OF PREPARER <u>A. W. Kapple</u> PHONE: (609) 365-7000 Salem Ext. 628