

July 17, 1979

Dr. T. G. Theofanous 132 Pathway Lane West Lafayette, IN 47906 REGULATORY DOCKET FILE COPY

Dear Dr. Theofanous:

EMERGENCY INSTRUCTIONS
NO. 2 UNIT
SALEM NUCLEAR GENERATING STATION

Enclosed for your use is a set of the Emergency Instructions (EI) for No. 2 Unit of the Salem Nuclear Generating Station. These EI's are being sent to you at the request of Mr. Elpidio Igne of the Advisory Committee on Reactor Safeguards.

The enclosed EI's are the latest revisions. Several of these EI's have been revised, but are still in the various stages of the review cycle. These particular EI's have therefore been stamped "For Information Only." It is expected that any subsequent changes would be merely of a cosmetic nature.

EI 4.7, "Steam Generator Tube Rupture" may be further revised, pending evaluation of further information not yet received.

Should you have any questions, please do not hestitate to contact us.

Very truly yours,

Ŕ. L. Mittl

General Manager -

Licensing and Environment Engineering and Construction

Enclosure

CC: E. Igne, ACRS

Olan D. Farr, USNRC

EO04

7907190588

NO

NO TE O

05-N94



July 17, 1979

Mr. Jesse Ebersole 103 Newell Lane Oak Ridge, TN 37830

Dear Mr. Ebersole:

EMERGENCY INSTRUCTIONS
NO. 2 UNIT
SALEM NUCLEAR GENERATING STATION

Enclosed for your use is a set of the Emergency Instructions (EI) for No. 2 Unit of the Salem Nuclear Generating Station. These EI's are being sent to you at the request of Mr. Elpidio Igne of the Advisory Committee on Reactor Safeguards.

The enclosed EI's are the latest revisions. Several of these EI's have been revised, but are still in the various stages of the review cycle. These particular EI's have therefore been stamped "For Information Only." It is expected that any subsequent changes would be merely of a cosmetic nature.

EI 4.7, "Steam Generator Tube Rupture" may be further revised, pending evaluation of further information not yet received.

Should you have any questions, please do not hestitate to contact us.

Very truly yours,

R. L. Mittl / Cll

General Manager -

Licensing and Environment Engineering and Construction

Enclosure

CC: E. Igne, ACRS
Olan D. Parr, USNRC

July 17, 1979

Mr. Carlyle Michelson 111 Vienna Rd. Oak Ridge, TN 37830

Dear Mr. Michelson:

EMERGENCY INSTRUCTIONS
NO. 2 UNIT
SALEM NUCLEAR GENERATING STATION

Enclosed for your use is a set of the Emergency Instructions (EI) for No. 2 Unit of the Salem Nuclear Generating Station. These EI's are being sent to you at the request of Mr. Elpidio Igne of the Advisory Committee on Reactor Safeguards.

The enclosed EI's are the latest revisions. Several of these EI's have been revised, but are still in the various stages of the review cycle. These particular EI's have therefore been stamped "For Information Only." It is expected that any subsequent changes would be merely of a cosmetic nature.

EI 4.7, "Steam Generator Tube Rupture" may be further revised, pending evaluation of further information not yet received.

Should you have any questions, please do not hestitate to contact us.

Very truly yours,

Ŕ. L. Mittl

General Manager -

Licensing and Environment Engineering and Construction

Enclosure

CC: E. Igne, ACRS

Olan D. Parr, USNRC



July 17, 1979

Dr. Ivan Catton 22436 Galilee St. Woodland Hills, CA 91364

Dear Dr. Catton:

EMERGENCY INSTRUCTIONS
NO. 2 UNIT
SALEM NUCLEAR GENERATING STATION

Enclosed for your use is a set of the Emergency Instructions (EI) for No. 2 Unit of the Salem Nuclear Generating Station. These EI's are being sent to you at the request of Mr. Elpidio Igne of the Advisory Committee on Reactor Safeguards.

The enclosed EI's are the latest revisions. Several of these EI's have been revised, but are still in the various stages of the review cycle. These particular EI's have therefore been stamped "For Information Only." It is expected that any subsequent changes would be merely of a cosmetic nature.

EI 4.7, "Steam Generator Tube Rupture" may be further revised, pending evaluation of further information not yet received.

Should you have any questions, please do not hestitate to contact us.

Very truly yours,

R. L. Mittl

General Manager -

Licensing and Environment Engineering and Construction

Enclosure

CC: E. Igne, ACRS

Olan D. Parr, USNRC .



July 17, 1979

Dr. Walter C. Lipinski Argonne National Laboratory 9700 South Cass Ave. Argonne, IL 60439

Dear Dr. Lipinski:

EMERGENCY INSTRUCTIONS
NO. 2 UNIT
SALEM NUCLEAR GENERATING STATION

Enclosed for your use is a set of the Emergency Instructions (EI) for No. 2 Unit of the Salem Nuclear Generating Station. These EI's are being sent to you at the request of Mr. Elpidio Igne of the Advisory Committee on Reactor Safeguards.

The enclosed EI's are the latest revisions. Several of these EI's have been revised, but are still in the various stages of the review cycle. These particular EI's have therefore been stamped "For Information Only." It is expected that any subsequent changes would be merely of a cosmetic nature.

EI 4.7, "Steam Generator Tube Rupture" may be further revised, pending evaluation of further information not yet received.

Should you have any questions, please do not hestitate to contact us.

Very truly yours,

R. L. Mittl

General Manager -

Licensing and Environment Engineering and Construction

Enclosure

CC: E. Igne, ACRS
Olan D. Parr, USNRC