

Frederick W. Schneider  
Vice President  
Production

Public Service Electric and Gas Company 80 Park Place Newark, N.J. 07101 201/430-7373

August 14, 1979

Mr. Boyce H. Grier, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region 1  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:


NRC IE BULLETIN NO. 79-06A, REV. 1  
NO. 1 AND 2 UNITS  
SALEM GENERATING STATION  
SUPPLEMENTAL INFORMATION

As additional information as requested by Mr. William Ross (NRC Staff) to our July 13, 1979 letter on the above subject, we offer the following information:

1. In reference to Item 9: the design changes to ensure the isolation of the RCDT line and the PRT line will be implemented prior to proceeding into Mode 4 operation following our present refueling outage.
2. In reference to Item 11: the Station Supervisory Letter, SL-9, "Notification of Federal and State Agencies" has been revised to include a description of the events or conditions requiring NRC notification within one hour that the reactor is not in a controlled or expected condition of operation.

If you require additional information, we will be pleased to discuss it with you.

Sincerely,



CC: NRC Office of Inspection & Enforcement  
Div. of Reactor Operations Inspection  
Washington, D.C. 20555

790921 0087

KB.  
A0<sub>2</sub>