CENTRAL FUES

## UNITED STATES

## NUCLEAR REGULATORY COMMISSION

REGION I 631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

DEC 1 2 1979

Docket No. 50-311

EAR REGULA,

STATE.

CO3LING

Public Service Electric & Gas Company ATTN: Mr. T. J. Martin Vice President Engineering and Construction 80 Park Place Newark, New Jersey 07101

Gentlemen:

Subject: Inspection 50-311/79-28

This refers to the inspection conducted by Dr. M. Shanbaky of this office on October 15-18, 1979 at Salem Nuclear Generating Station, Hancocks Bridge, New Jersey of activities authorized by NRC License No. CPPR-53 and to the discussions of our findings held by Dr. Shanbaky with Messrs. R. Griffith and D. Cooley and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the Office of Inspection and Enforcement Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must be accompanied by an affidavit executed by the owner of the information, which identifies the document or part sought to be withheld, and which contains a statement of reasons which addresses with specificity the items which will be considered by the Commission as listed in subparagraph (b) (4) of Section 2.790. The information sought to be withheld shall be incorporated as far as possible into a separate part of the affidavit. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

8001310 173

Public Service Electric and Gas Company

DEC 1 2 1979

No reply to this letter is required; however, should you have any questions concerning this inspection, we will be pleased to discuss them with you.

FOR

2

Sincerely,

George H. Smith, Chief Fuel Facility and Materials Safety Branch

Enclosure: Office of Inspection and Enforcement Inspection Report Number 50-311/79-28

cc w/encl:

(

.

E. N. Schwalje, Manager - Quality Assurance, Engineering and Construction Department

## U. S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

11

REGION I

Report No. <u>50-311/79-28</u>
Docket No. <u>50-311</u>
License No. <u>CPPR-53</u> Priority <u></u> Category <u>B-1</u>
Licensee: <u>Public Service Electric &amp; Gas Company</u>
80 Park Place
Newark, New Jersey
Facility Name: <u>Salem Nuclear Generating Station, Unit 2</u> (SNGS-2)
Inspection At: <u>Hancocks Bridge, New Jersey</u>
Inspection Conducted: October 15-18, 1979
Inspectors: M. Shanbaky 12/5/79
M. M. Shanbaky, Radiation Specialist date $\frac{12/4}{79}$
T. J. Dackson, Radiation Specialist (Intern) date
date date
Approved by: R. J. Boyes, Acting Chief, E&SP Section, <i>R. J. Boyes</i> , Acting Chief, E&SP Section, date
FF&MS <sup>®</sup> Branch
<u>Inspection Summary</u> : Inspection on October 15-18, 1979 (Report No. 50-311/79-28)
Areas Inspected: Routine, unannounced inspection of preoperation environmental

<u>Areas Inspected</u>: Routine, unannounced inspection of preoperation environmental monitoring programs at SNGS-2 including: preoperational environmental monitoring requirements; licensee preparedness status to implement the operational environmental monitoring program when required upon issuance of the Operating License; and, compliance with the Construction Permit requirements for environmental protection during construction. The inspection involved 24 inspector-hours onsite by two regionally based NRC inspectors.

Results: Of the three areas inspected, no items of noncompliance were found.

Region I Form 167 (August 1979)