

LICENSEE EVENT REPORT

CONTROL BLOCK: ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

① 01 | ② N J S G S 2 | ③ 00 - 000000 - 000 | ④ 4 1 1 1 1 | ⑤

CON'T ① 01 | REPORT SOURCE | ⑥ L | ⑦ 05000311 | ⑧ 082080 | ⑨ 091880

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

① 02 | During routine surveillance of the control console, it was determined that the
① 03 | level in the RWST was below the minimum level of 364,500 gallons. Action
① 04 | Statements 3.1.2.8b and 3.5.5 were entered at 0045 hours and a cooldown was
① 05 | initiated at 0130 hours (docket 50-272, 80-43).
① 06 |
① 07 |
① 08 |

① 09 | SYSTEM CODE [S F] ⑪ | CAUSE CODE [E] ⑫ | CAUSE SUBCODE [B] ⑬ | COMPONENT CODE [Z Z Z Z Z Z] ⑭ | COMP. SUBCODE [Z] ⑮ | VALVE SUBCODE [Z] ⑯

⑰ LER/RO REPORT NUMBER [8 0] | EVENT YEAR [] | SEQUENTIAL REPORT NO. [0 2 8] | OCCURRENCE CODE [] | REPORT TYPE [L] | REVISION NO. [0]

ACTION TAKEN [B] ⑱ | FUTURE ACTION [Z] ⑲ | EFFECT ON PLANT [Z] ⑳ | SHUTDOWN METHOD [Z] ㉑ | HOURS [0 0 0 0] ㉒ | ATTACHMENT SUBMITTED [Y] ㉓ | NRPD-4 FORM SUB. [N] ㉔ | PRIME COMP. SUPPLIER [Z] ㉕ | COMPONENT MANUFACTURER [Z 9 9 9] ㉖

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

① 10 | A hose failed on a temporary demineralizer being used to purify RWST water. The
① 11 | RWST was refilled to > 364,500 gallons. The Action Statement was terminated at
① 12 | 0830 hours. The failed hose was replaced.
① 13 |
① 14 |

① 15 | FACILITY STATUS [B] ㉘ | % POWER [0 0 0] ㉙ | OTHER STATUS [NA] ㉚ | METHOD OF DISCOVERY [B] ㉛ | DISCOVERY DESCRIPTION [Operator Observation] ㉜

① 16 | ACTIVITY RELEASED [Z] ㉝ | CONTENT [Z] ㉞ | AMOUNT OF ACTIVITY [NA] ㉟ | LOCATION OF RELEASE [NA] ㊱

① 17 | PERSONNEL EXPOSURES NUMBER [0 0 0] ㊲ | TYPE [Z] ㊳ | DESCRIPTION [NA] ㊴

① 18 | PERSONNEL INJURIES NUMBER [0 C 0] ㊵ | DESCRIPTION [NA] ㊶

① 19 | LOSS OF OR DAMAGE TO FACILITY TYPE [Z] ㊷ | DESCRIPTION [NA] ㊸

① 20 | PUBLICITY ISSUED [N] ㊹ | DESCRIPTION [NA] ㊺

8009280 694

NRC USE ONLY

NAME OF PREPARER J. M. Randolph PHONE: 609-935-0998