U. S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

REGION I

. •	
Report No.	50-272/80-17 <u>50-311/80-13</u> 50-272 DPR-70
Docket No.	
Licensee:	Public Service Electric and Gas Company -
	80 Park Place
•	Newark, New Jersey 07101
Facility N	ame: Salem Nuclear Generating Station, Units 1 and 2
Inspection	At: Hancocks Bridge, New Jersey
Inspection	Conducted: July 14-18, 1980
Date of Last Physical Security Inspection Visit: May 19-21, 1980	
Type of Inspection: Routine, Unannounced, Physical Security	
Inspectors	Roland J. Bailey, Physical Security Inspector // date
	Notalia of Satisfy Thysical Population
	date
	date
Approved b	Charles Mala
	James W. Devlin, Chief, Security and Investigation Section, Safeguards Branch
Inspection	Summary: on July 14-18,1980 (Combined Inspection Reports Nos. 50-272/80-17/50-311/80-13
Areas Inspected: Physical security inspection, of the approved physical security plan, security program audit, security organization, physical barriers (PA/VA), lighting,	
access control (search) (escorting), (vital areas), alarm station, detection aids,	
assessment aids, communications, testing and maintenance, compensatory measures, power supply, response, locks, keys and combinations and records and reports.	
The inspection involved 39 inspector-hours onsite by a regional based inspector. The inspection was begun during regular hours.	
Results:	The licensee was found to be in noncompliance with the Physical Security
inspection	RC requirements within three(3) of the nineteen areas examined during the , i.e., (a) failure to keep the isolation zone clear of structures or
material,	(b) failure to secure an opening in the wall of the control and auxiliary

8011180450

relay room, (c) failure to secure an opening above a partition that was part of a vital area barrier. Two unresolved items are: (a)bullet resistant requirements at the contractor access control point, and (b) recording exit times from normally

unoccupied vital areas.