



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION I  
631 PARK AVENUE  
KING OF PRUSSIA, PENNSYLVANIA 19406

CENTRAL FILES

MAY 14 1981

Docket Nos. 50-272  
50-311

Public Service Electric and Gas Company  
ATTN: Mr. F. W. Schneider  
Vice President - Production  
80 Park Place - 15A  
Newark, New Jersey 07101



Gentlemen:


Subject: Combined Inspection 50-272/81-01 and 50-311/81-01

This refers to your letter dated April 2, 1981, in response to our letter dated March 12, 1981.

Thank you for informing us of the corrective and preventive actions documented in your letter. Based on discussions between Mr. L. Norrholm of this office and Mr. J. Zupko of your staff on April 27, 1981 we understand that, with respect to Item B, a hardware modification to provide an operator aid in resolving this recurring problem will be implemented by the end of the next refueling outage. With respect to Item C, we understand that Procedure AP-16 addressing 10 CFR 19 posting requirements will be issued by May 21, 1981. These actions will be examined during a future inspection of your licensed program. If our understanding of your preventive actions is incorrect, please advise this office within 10 days.

Your cooperation with us is appreciated.

Sincerely,

  
R. R. Keimig, Chief  
Projects Branch #2, DRPI

cc:

J. T. Boettger, General Manager - Corporate Quality Assurance  
R. L. Mittl, General Manager - Licensing and Environment  
H. J. Midura, Manager - Salem Generating Station  
R. A. Uderitz, General Manager - Nuclear Production

8106050271