DMBOK

AUG 2 4 1981

DISTRIBUTION Docket File NRC PDR Local PDR TERA NSIC ACRS (10) ORB 1 File D. Eisenhut S. Varga 01-6-C. Parrish 1981 0 W. Ross U.S. NUCLEAR REGULATONS OELD COMMISSION I&E (3) G. Meyer C. Trammell

Docket Nos. 50-272 and 50-311

> Mr. F. W. Schneider, Vice President Production Public Service Electric and Gas Company 80 Park Plaza 15A Newark, New Jersev 07101

Dear Mr. Schneider:

This letter documents the close-out for Salem Units 1 and 2 of four items from NUREG-0737, "Clarification of TMI Action Plan Requirements." We are providing this written notification at this time to ensure that PSE&G and the NRC continue to maintain clear and consistent records of the status of these items. Similarly, in the future we shall notify you of the close-out of each Action Plan item: as it occurs.

The following four Action Plan items have been completed for Salem Units 1 and 2.

- 1. Item II.K.3.9 -- Your letters of December 15, 1980 (Docket No. 50-272) and May 20, 1980 (Docket No. 50-311) indicate you have taken the actions requested under item: II.K.3.9 (PID Controller) of NUREG-0737. Therefore, this item is resolved for your facility.
- 2. Item II.K.3.10 -- Your letters of December 15, 1980 (Docket No. 50-272) and May 20, 1980 (Docket No. 50-311) indicate that no increase in the setpoint for the reactor trip on turbine trip is contemplated, and therefore item II.K.3.10 is resolved for your facility.
- 3. Item II.K.3.12 -- Your letters of December 15, 1980 (Docket No. 50-272) and May 20, 1980 (Docket No. 50-311) confirm that Salem Units 1 and 2 have an anticipatory reactor trip on turbine trip, in conformance with item II.K.3.12 of NUREG-0737. Therefore, this item is resolved.

OFFICE	8109180	0643 810824 ОСК 05000272	······································				••••••
SURNAME	P ADE	JCK 05000272		····	•••••		••••••
NRC FOEM 318 (10-80) NRCM 0240			OFFICIAL	RECORD C	OPY	· · · · · · · · · · · · · · · · · · ·	USGPO: 1981-335-960

Mr. F. W. Schneider

4. Item II.E.4.1 -- Your letters of December 15, 1980 (Docket No. 50-272) and December 15, 1980 (Docket No. 50-311) confirms that Salem Units 1 and 2 have redundant recombiner systems inside containment and hence item II.E.4.1 is not applicable. Therefore, this item is resolved.

If you have any questions regarding the status of these items, please contact us.

Sincerely,

Original Signed By:

Steven A. Varga, Chief Operating Reactors Branch No. 1 Division of Licensing

cc: See next page

