



Public Service Electric and Gas Company P.O. Box E Hancocks Bridge, New Jersey 08038

Salem Generating Station

May 06, 1988

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Dear Sir:

SALEM GENERATING STATION
LICENSE NO. DPR-70
DOCKET NO. 50-272
UNIT NO. 1
SPECIAL REPORT 88-1

This Special Report was issued originally on May 5, 1988 with the wrong cover letter. The report addresses fire barrier penetration impairments which have not been restored to functional status within seven (7) days and not missed fire watches associated with Salem Unit 2 Special Report 88-3 as stated in the originally issued cover letter.

This report satisfies the reporting requirements of Technical Specification Action 3.7.11.a pursuant to Technical Specification 6.9.2. It is being submitted within thirty (30) days as per the Action Statement.

Sincerely yours,

John Zupko
J. M. Zupko, Jr.
General Manager-
Salem Operations

MJP:pc

Distribution
The Energy People

8805120003 880506
PDR ADOCK 05000272
S DCD

IE22
||