

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

716 Edney Building

November 7, 1979

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFRO-50-296/796

The enclosed report is a supplement to the June 5, 1979, letter from
H. S. Fox concerning an erratic indication of the torus hydrogen sensor,
H₂M-76-38, which was observed during normal operation. This report is
submitted in accordance with Browns Ferry unit 3 Technical Specification
6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

R. F. Sullivan, NRC Inspector, Browns Ferry

7911140 351

A002
5/11
5

UNITED STATES DEPARTMENT OF THE ARMY

HEADQUARTERS, 10TH AVIATION BRIGADE

10 AVIATION BRIGADE

MEMORANDUM FOR THE RECORD
SUBJECT: [Illegible]

[Illegible text]

[Illegible text]

[Illegible text]

[Illegible text]

[Illegible text]

041185